

SoCalGas-46

SED's Draft Opening Testimony (Nov. 14, 2019)

I.19-06-016

ALJs: Hecht/Poirier

Date Served: March 15, 2021

Docket: : I.19-06-016
Exhibit Number : _____
Commissioner : _____
Admin. Law : _____
Judge : _____
ORA Project Mgr. : _____



SAFETY AND ENFORCEMENT DIVISION
California Public Utilities Commission

**OPENING TESTIMONY OF THE SAFETY AND ENFORCEMENT DIVISION
REGARDING**

San Francisco, California
November 14, 2019

320168187

EXHIBIT
- 18
Margaret Felts
2/5/2020
Linda Ryan, CSR 9915

TABLE OF CONTENTS

	<u>PAGE</u>
I. INTRODUCTION.....	1
II. BACKGROUND.....	1
A. Summary of Incident and Violations	1
B. Root Causes and Direct Causes Related to the Uncontrolled Release of Hydrocarbons for 111 Days from Well SS-25, and Resulting Violations of Section 451.....	6
1. SoCalGas Failed to Perform Failure Investigations, Failure Analyses or Root Cause Analyses on Failed Aliso Canyon Wells Despite More Than 60 Well Casings Experiencing Leaks, Four Having Parted Casings, and Several Wells Having Casing Corrosion Identified. Therefore, SoCalGas Did Not Properly Understand The Extent and Consequences of the Corrosion in the Other Wells, Including Well SS-25.....	6
a) SoCalGas Did Not Investigate or Analyze its Past Casing Leaks of Other Wells at Aliso Canyon, and the Consequences of Corrosion in these Other Wells Was Not Understood.....	6
b) SoCalGas Did Not Properly Follow Its Own 1988 Plan to Determine the Condition of the Casing in 12 Wells.....	9
c) SoCalGas Failed to Discover Specific Corrosion Problems on Well SS-25.....	10
2. SoCalGas did not have any form of risk assessment focused on wellbore integrity management, including lack of assessment of qualitative probability and consequences of production casing leaks or failures.....	12
a) SoCalGas Did Not Implement A Risk Assessment Program or Wellbore Integrity Management Plan at Aliso Canyon Storage Facility Prior to October 23, 2015	12
b) SoCalGas’s Failure to Implement A Risk Assessment Program or Wellbore Integrity Management Plan at Aliso Canyon Storage Facility Prior to October 23, 2015 Resulted in the Failure to Detect Corrosion on the Well SS-25 Seven Inch Casing Prior to October 23, 2015	16
c) SoCalGas Did Not Start a Storage Integrity Management Program in 2009, Even Though It Was Recommended by Its Storage Engineering Manager at that Time, Because They Could Not Yet Collect It in Rates.....	17

3.	SoCalGas did not have a dual mechanical barrier system in the wellbore of SS-25, instead leaving the 7-inch production casing as the primary barrier to the gas.	18
4.	SoCalGas did not have internal policies that required inspection and measurement of the wall thickness of wellbores at Aliso. Instead, SoCalGas used techniques that detected and fixed leaks only after an event occurred.	25
5.	SoCalGas did not have a well specific, well control plan that considered transient kill modeling or well deliverability. There was not quantitative understanding of well deliverability, although data were available, and well-established industry practices existed for such analysis.	27
6.	SoCalGas did not employ reasonable understanding of the groundwater depths relative to the surface casing shoe and production casing of well SS-25, until two groundwater wells were drilled for RCA purposes after the October 23, 2015 incident at SS-25.	39
	a) Groundwater Caused Corrosion on the Corrosion on the 7 Inch and 11 ¼ Inch Casings on SS-25	39
	b) SoCalGas Did Not Assess the Relationship Between Groundwater In and Around the SS-25 Well Site, and The Surface Casing Corrosion of That Well.	45
7.	SoCalGas did not have systematic practices to protect surface casing strings against external corrosion. Therefore, SoCalGas did not employ proper understanding of the consequences of corroded surface casings and uncemented production casings.	46
8.	SoCalGas lacked a real-time, continuous pressure monitoring system for well surveillance, which prevented an immediate identification of the SS-25 leak and accurate estimation of the gas flow rate.	48
C.	Additional Violations	52
	1. SoCalGas Knew that SS-25 Released Both Crude Oil and Natural Gas During the Aliso Canyon Natural Gas Storage Incident, But Did Not Disclose This Fact to the Los Angeles County Department of Public Health	52
	2. In Multiple Instances, SoCalGas Did Not Cooperate with SED During Its Pre-Formal Investigation Following the Incident on Aliso Well SS-25 that Began on October 23, 2015	53

D.	Example 1: SoCalGas Did Not Completely Answer the Discovery of the Aliso Root Cause Analysis Consultants, Blade Energy Partners, and Then Provided a Data Dump As a Supplement These Incomplete Responses Up to Three Years Later, and Weeks Before Blade’s Announced Release Date of Its Root Cause Analysis.....	54
E.	Example 2: Despite SED’s Subpoenas to Do So, SoCalGas Did Not Produce Boots and Coots’s Team Lead Well Kill Specialist, and Another Boots & Coots Safety Representative, Both of Whom Were Onsite for Certain of the Boots & Coots Efforts to Kill Well SS-25, for SED to Examine Under Oath	55
F.	Example 3: Despite SoCalGas Not Producing Boots & Coots’s Team Lead Well Kill Specialist, It Refused to Provide Certain Communications Between SoCalGas and Boots & Coots, Including Some Between that Individual and SoCalGas’s President and CEO, Claiming Them to Be Privileged As Attorney-Client Communications. SoCalGas Later Revealed Some of the Communications It Initially Claimed to Be Privileged by Attorney-Client Communications	61
G.	Example 4: Blade Asked for Boots and Coots to Appear for Blade to Interview Them as Part of Blade’s Root Cause Analysis, But SoCalGas Failed to Produce Boots and Coots for This Purpose	64
H.	Example 5: In Response to SED’s Question Asking Whether SoCalGas Disclosed to Non-SoCalGas Entities Anything that Would Reveal That SED Was Conducting EUO’s, SoCalGas Revealed that It Had Communicated with Counsel representing Pacific Gas and Electric Company and Counsel Representing Southern California Edison Company	65
I.	Example 6: SoCalGas Intentionally Did Not Appear for a Deposition Despite of a Commission-Issued Subpoena Requiring It to Do So.....	66
	3. <i>“SoCalGas has consistently cooperated with SED’s investigation and, in fact, that was the purpose of my call yesterday. I left you a courtesy voicemail letting you know that were filing our motion to quash today so that you could timely cancel the court reporter. . .To confirm your understanding: we are filing the motion to quash today and we will not be attending the deposition tomorrow. (Emphasis added).</i>	67
	1. SoCalGas Did Not Keep Traceable, Verifiable, Complete or Accurate Records That Were Necessary for the Safe Operation and Maintenance of Its Wells at Aliso Canyon Natural Gas Storage Facility	67

1 **I. INTRODUCTION**

2 On May 16, 2019, Blade Energy Partners (Blade) published an independent root
3 case analysis RCA report, “Root Cause Analysis of the Uncontrolled Hydrocarbon
4 Release from Aliso Canyon SS-25”. Drawing on the Blade report and information
5 obtained in its own investigation, this testimony identifies numerous safety [and health]
6 violations of California Public Utilities Code Section 451¹ related to the uncontrolled
7 release of hydrocarbon gas or methane for 111 days from Southern California Gas
8 Company’s (SoCalGas) Aliso Canyon Well SS-25 (SS-25 incident),² including many
9 different causes identified in the Blade Report from which the SS-25 incident resulted. In
10 addition, the testimony identifies multiple instances in which SoCalGas did not cooperate
11 with the investigation of the Safety and Enforcement Division (SED), resulting in
12 additional violations of Section 451, and certain violations of California Public Utilities
13 Commission’s Rule of Practice and Procedure (Rule) 1.1. Finally, the testimony
14 identifies violations of Section 451 due to SoCalGas’s recordkeeping problems related to
15 the Aliso Canyon storage facility, and to the SS-25 incident.

16 **II. BACKGROUND**

17 **A. Summary of Incident and Violations**

18 At 3:15 PM on October 23, 2015, a leak was discovered in the Standard Sesnon 25
19 (SS-25) well.³ SS-25 was shut in⁴ at 3:30 PM that day, and flowed uncontrollably for
20 111 days. Blade Energy Partners estimates that approximately 6.6 Billion Cubic Feet
21 (BSCF) of natural gas, or approximately 120,000 metric tons of methane had leaked.⁵

¹ California Public Utilities Code Section 451 will also be referred to as “Section 451” or “451”.

² See “Root Cause Analysis of the Uncontrolled Hydrocarbon Release from Aliso Canyon SS-25”,
May 16, 2019. (Blade Report), p. 4. The Blade Report can be viewed at:
ftp://ftp.epuc.ca.gov/News_and_Outreach/SS-25%20RCA%20Final%20Report%20May%2016,%202019.pdf

³ Root Cause Analysis of the Uncontrolled Hydrocarbon Release from Aliso Canyon SS-25, Blade Energy Partners,
May 16, 2019 (Blade Report) at p. 2.

⁴ The Blade Report at p. 133 uses the term “shut in” interchangeably with “not flowing”.

⁵ Blade Report, p. 13; Blade Report at p. 155, Table 26: Aliso Canyon Hydrocarbon Leak Estimates. According to
the Blade Report, Table 26, the California Air Resources Board (CARB) estimated that 6.0 BSCF of gas, or
approximately 109 cubic tons of the methane equivalent had leaked by well SS-25.

1 SoCal Gas and its hired well control company, Boots and Coots,⁶ made seven
2 unsuccessful attempts to kill well SS-25 by pumping down the tubing and casing.⁷ ⁸
3 Ultimately, relief well P-39A was drilled, enabling SS-25 to be successfully killed in
4 February 2016, four months after the leak had started.⁹ The Los Angeles County
5 Department of Public Health observed that, “the health of nearby residents may have
6 been impacted by exposure to both crude oil and natural gas during the Disaster”.¹⁰
7 SoCalGas also failed to investigate in multiple instances with SED during the course of
8 its investigation.

9 California Public Utilities Code Section 451 provides in part,

10 Every public utility shall furnish and maintain such adequate, efficient, just, and
11 reasonable service, instrumentalities, equipment, and facilities. . . as are necessary to
12 promote the safety, *health*, comfort, and convenience of its patrons, employees, and the
13 public. (Emphasis added.)

14 Table 1 below summarizes the violations found by SED associated with this
15 incident, and identifies the section of testimony where the factual basis can be found for
16 each violation. Except where explicitly provided in Table 1, each violation identified in
17 Table 1 is a violation of California Public Utilities Code Section 451 (Section 451).

⁶ Southern California Gas Company Standard Services Agreement (Agreement 5660044243), Project Standard
Senson (Sic) 25, October 30, 2015. (SoCalGas and Boots and Coots Well Kill Agreement).

⁷ Blade Report at p. 172.

⁸ According to the SoCalGas and Boots and Coots Well Kill Agreement, p. 1 of 21, the name of the well control
company that SoCalGas hired is Boots and Coots. Though Boots and Coots were requested to kill the well,
Halliburton Energy Services entered into the contract with SoCalGas.

⁹ Blade Report at p. 172.

¹⁰ Letter from Los Angeles County Department of Public Health, Deputy Director for Health Protection, Angelo J.
Bellomo, MS, REHS, QEP, to SoCalGas Chief Executive Officer, Brett Lane, March 11, 2019, page 2. Available
at:
https://www.epuc.ca.gov/uploadedFiles/CPUCWebsite/Content/News_Room/NewsUpdates/2019/Aliso%20Canyon%20Facility.pdf

Table 1: Summary of Violations¹¹

Violation Number	Summary of Violation	Begin Date	End Date	Testimony Section Number
1	No investigation of blowout from well Frew-3.	12/31/1984	10/23/2015	II.B.1.a
2	No investigation blowout from well FF-34A.	12/31/1990	10/23/2015	II.B.1.a
3	No investigation of one of four parted well casings.	12/31/1969	10/23/2015	II.B.1.a
4 through 6	No investigation of any of three parted well casings.	12/31/1994	10/23/2015	II.B.1.a
7 through 60	No investigation of 54 well leaks.	10/22/2015	10/23/2015	II.B.1.a
61 through 72	Failure to follow company's internal 1988 plan to check casing of 12 wells for metal loss.	8/31/1988	10/23/2015	II.B.1.b
73	Failure to follow company's internal 1988 plan to check casing of well SS-25 for metal loss.	8/31/1988	10/23/2015	II.B.1.b
74	Failure to implement a risk or integrity management program for Aliso Canyon storage facility (Aliso).	12/31/2009	10/23/2015	II.B.2.a
75	Failure to detect corrosion on well SS-25 resulting in part from lack of risk assessment at Aliso.	12/31/2009	10/23/2015	II.B.2.b
76	Failure to start well integrity program in 2009 because of inability to collect recovery for it in rates.	12/31/2009	10/23/2015	II.B.2.c
77	Operation of well SS-25 without backup mechanical barrier to 7-inch production casing.	8/31/1988	10/23/2015	II.B.3
78	Operation of Aliso without internal policies that required well casing wall thickness inspection and measurement.	8/31/1988	10/23/2015	II.B.4
79	Failure to successfully execute well SS-25 kill attempt numbers 2 through 7, due to lack of proper modelling.	11/13/2015	2/11/2016	II.B.5
80 through 82	Failure to provide well kill programs for relief well #2, well SS-25A and well SS-25B.	11/13/2015	2/11/2016	II.B.5
83	Prevention of surface plumbing failures on SS-25 from enabling that well to be kept filled.	11/25/2015	2/11/2016	II.B.5
84	Allowance of groundwater to cause corrosion on the 7 inch and 11 3/4 inch casings on SS-25.	8/31/1988	10/23/2015	II.B.6

¹¹ SED reserves the right to update these violations and the dates associated with them if SED becomes aware of information that requires doing so.

Violation Number	Summary of Violation	Begin Date	End Date	Testimony Section Number
85	Failure to assess the relationship between groundwater in and around the SS-25 wellsite and surface casing corrosion of SS-25.	8/31/1988	10/23/2015	II.B.6
86	Failure to have systematic practice to protect surface casing strings against external corrosion and failure to employ proper understanding of the consequences of corroded surface casings and uncemented production casings.	8/31/1988	10/23/2015	II.B.7
87	Failure to have continuous pressure monitoring system for well surveillance because it prevented an immediate identification of the SS-25 leak and accurate estimation of the gas flow rate.	10/23/2015	2/12/2016	II.B.8
88	Failure to disclose to Los Angeles County Department of Public Health Known Facts that crude oil was released from well SS-25 during the incident.	11/15/2015	2/12/2016	II.C.1
89	Lack of Cooperation: Failure to completely respond to Blade Root Cause Analysis related data requests on January 31, 2016 until no sooner than March 1, 2019.	3/31/2016	3/1/2019	II.C.2 Example 1
90	Lack of Cooperation: Failure to completely respond to Blade Root Cause Analysis related data requests on February 19, 2016 until no sooner than March 1, 2019.	4/18/2016	3/1/2019	II.C.2 Example 1
91	Lack of Cooperation: Failure to completely respond to Blade Root Cause Analysis related data requests on April 7, 2016 until no sooner than March 1, 2019.	6/7/2016	3/1/2019	II.C.2 Example 1
92	Lack of Cooperation: Failure to completely respond to Blade Root Cause Analysis related data requests on February 18, 2018 until no sooner than March 1, 2019.	4/7/2016	3/1/2019	II.C.2 Example 1
93 through 94	Lack of Cooperation: Failure to produce two individuals from Boots & Coots present during the well kill efforts, despite an SED subpoena to do so.	8/8/2018	11/22/2019	II.C.2 Example 2

Violation Number	Summary of Violation	Begin Date	End Date	Testimony Section Number
95 through 189	Lack of Cooperation: Refusal to release 95 pages of communications based upon assertion of attorney-client and/or attorney work product privilege.	3/5/2018	1/3/2019	II.C.2 Example 3
190 through 284	Lack of Cooperation: Misleading SED by representing to SED that 95 pages of documents are protected by attorney-client/attorney work product privilege, when they were not.	3/5/2018	1/3/2019	II.C.2 Example 3
285 through 302	Lack of Cooperation: Refusal to release 18 additional communications based upon assertion of attorney-client and/or attorney work product privilege.	3/5/2018	5/11/2019	II.C.2 Example 3
303 through 320	Lack of Cooperation: Misleading SED by representing to SED that 18 additional communications were protected by attorney-client or attorney work product privilege, when they were not.	3/5/2018	5/11/2019	II.C.2 Example 3
321	Lack of Cooperation: Failure to produce those individuals from Boots & Coots requested for interviews by Blade Energy Partners as part of their Root Cause Analysis.	1/24/2019	5/19/2019	II.C.2 Example 4
322 through 323	Lack of Cooperation: Breach of confidentiality promise by communicating with PG&E and Southern California Edison counsel about certain aspects of SED's Examinations Under Oath of SoCalGas.	8/14/2018	6/26/2019	II.C.2 Example 5
324 through 325	Lack of Cooperation: Breach of confidentiality promise by communicating with PG&E and Southern California Edison counsel about certain aspects of SED's Examinations Under Oath of SoCalGas. (Rule 1.1 Violation)	8/14/2018	6/26/2019	II.C.2 Example 5
326	Lack of Cooperation: Intentionally not appearing at an SED deposition in spite of a Commission subpoena to do so.	11/1/2019	Pending	II.C.2 Example 6

1 **B. Root Causes and Direct Causes Related to the Uncontrolled Release of**
2 **Hydrocarbons for 111 Days from Well SS-25,¹² and Resulting**
3 **Violations of Section 451**

4 The Blade Report identifies several causes related to the SS-25 incident. In this
5 subsection, SED identifies a number of violations of Section 451 in this section that are
6 based upon causes identified in the Blade Report. Because SoCalGas could have
7 requested ratepayer money to pay for safety-related Operation and Maintenance for Aliso
8 Canyon storage facility in its General Rate Cases, its failure to implement the measures
9 identified in this section worsens each of the identified violations of Section 451.

10 **SoCalGas Failed to Perform Failure Investigations, Failure**
11 **Analyses or Root Cause Analyses on Failed Aliso Canyon Wells**
12 **Despite More Than 60 Well Casings Experiencing Leaks, Four**
13 **Having Parted Casings, and Several Wells Having Casing**
14 **Corrosion Identified. Therefore, SoCalGas Did Not Properly**
15 **Understand The Extent and Consequences of the Corrosion in**
16 **the Other Wells, Including Well SS-25.¹³**

17 SED finds multiple separate violations of Section 451 related to SoCalGas's
18 behavior regarding its awareness of well casing metal loss and metal loss threats to Aliso
19 Canyon well casings, as identified in this section.

20 **a) SoCalGas Did Not Investigate or Analyze its Past Casing**
21 **Leaks of Other Wells at Aliso Canyon, and the**
22 **Consequences of Corrosion in these Other Wells Was Not**
23 **Understood**

24 A root cause for the SS-25 incident was the lack of detailed follow-up
25 investigation, failure analyses, or RCA of casing leaks, parted casings, or other failure
26 events in the field in the past.¹⁴ There had been over 60 casing leaks at Aliso Canyon
27 before the SS-25 incident, but no failure investigations were ever conducted.¹⁵ Based on
28 the data reviewed by Blade, no investigation of the causes was performed, and, therefore,

¹² If SED becomes aware of additional information that could modify SED's findings, SED reserves the right to supplement or modify its testimony with updated information, or take further actions as appropriate.

¹³ Blade Report at p. 4.

¹⁴ Blade Report at p. 4.

¹⁵ Blade Report at p. 4.

1 the extent and consequences of the corrosion in the other wells were not understood.¹⁶
2 Furthermore, external corrosion on production casing had been identified in several
3 wells.¹⁷

4 The Aliso Canyon storage wells had numerous casing leaks.¹⁸ Blade reviewed 124
5 gas storage wells and identified 63 casing leaks, 29 tight spots,¹⁹ 4 parted casings, and 3
6 other types of failures.²⁰ Forty percent of the gas storage wells reviewed by Blade had
7 casing failures with an average of two casing failures per well.²¹

8 In addition, two Aliso Canyon wells had underground blowouts from casing leaks:
9 Frew-3 in 1984 and FF-34A in 1990.²² These wells were successfully killed by pumping
10 fluid down the tubing, and the consequences of a larger leak or a near-surface casing
11 rupture were not anticipated until the SS-25 event.²³

12 Between 1969 and 1994, four wells were discovered to have parted casings.²⁴
13 However, Blade found no evidence of RCA's, failure samples collected, lab analysis,
14 photos of failures, or failure analyses reports in the wells' files.²⁵ The only documents
15 found were well operations daily reports where on-site rig activities were reported.²⁶
16 Additionally, the FF-34A well file mentioned a study of the possible external casing
17 corrosion problems in the southeastern portion of the field, but Blade was not able to

¹⁶ Blade Report at pp.4, 219 and 237.

¹⁷ Blade Report at p. 4.

¹⁸ Blade Report at p. 2

¹⁹ According to the Blade Report at p. 162, a "tight spot" occurs "where the casing fails to perform in the manner it was designed for".

²⁰ Blade Report at p. 2.

²¹ Blade Report at pp. 2, 203. Page 203 quantifies this as 99 failures in 49 wells.

²² Blade Report at p. 2.

²³ Blade Report at p. 2.

²⁴ Blade Report at p. 165.

²⁵ Blade Report at p. 165.

²⁶ Blade Report at p. 165.

1 locate any documentation related to this study.²⁷ Consequently, there was no insight into
2 why these failures were happening.

3 SED views SoCalGas's failure to investigate or analyze the failures or root causes
4 of casing leaks, parted casings, or other failure events as separate violations of Section
5 451, as follows:

- 6 • One violation for failure to investigate the blowout from
7 well Frew-3 spanning from December 31, 1984, the last
8 possible date of the blowout,²⁸ to October 23, 2015, the
9 date of the incident.
- 10 • One violation for failure to investigate the blowout from
11 well FF-34A, spanning from December 31, 1990, the last
12 possible date of the blowout,²⁹ to October 23, 2015, the
13 date of the incident.
- 14 • Four violations: One for failure to investigate each of the
15 parted casings discovered between 1969 and 1994. As
16 one of the parted casings must have been discovered in
17 1969 to set the beginning of the range, that first violation
18 spans from December 31, 1969 the last possible date of its
19 parting, to October 23, 2015, the date of the incident.
20 Assuming that the remaining three parted casings were
21 discovered December 31, 1994, those three separate
22 violations each span from, at the latest, December 31,
23 1994 to October 23, 2015.³⁰
- 24 • To avoid double counting violations, SED assumes that
25 the 60 leaks identified before the Aliso Canyon incident
26 included the six blowouts and parted casings identified
27 above. As such, the remaining 54 leaks that went without
28 investigation should constitute a separate set of up to 54
29 violations. At the latest, these violations began on

²⁷ Blade Report at p.2.

²⁸ If SED becomes aware of additional information that could modify SED's findings, SED reserves the right to supplement or modify its testimony with updated information as to the point in time when this blowout occurred, or take further actions as appropriate.

²⁹ If SED becomes aware of additional information that could modify SED's findings, SED reserves the right to supplement or modify its testimony with updated information as to the point in time when this blowout occurred, or take further actions as appropriate.

³⁰ If SED becomes aware of additional information that could modify SED's findings, SED reserves the right to supplement or modify its testimony with updated information as to the points in time these parted casings were discovered, or take further actions as appropriate.

1 October 22, 2015, the last possible date before the incident
2 on October 23, 2015.³¹

3 **b) SoCalGas Did Not Properly Follow Its Own 1988 Plan to**
4 **Determine the Condition of the Casing in 12 Wells³²**

5 SoCalGas had a two-year plan in 1988 to determine the mechanical condition of
6 the casing in 20 casing flow wells originally completed in the 1940s and 1950s.³³ The
7 wells, including SS-25, were prioritized based on gas deliverability, operational history,
8 and length of time since their last workover.³⁴ SS-25 was given a low priority.³⁵ Of the
9 20 wells, SoCalGas ran inspection logs in seven within two years of the 2 year plan
10 window.³⁶ The inspection logs showed metal loss indications on the outside diameter
11 (OD) of the casing ranging from 20% to 60% of the wall thickness in 5 of the 7 wells
12 logged from 1988 to 1990.³⁷ Some of the wells had indications above the surface casing
13 shoe, and many had indications below the casing shoe.³⁸ Blade found no documentation
14 indicating that investigations into the causes of external corrosion, on any of these wells,
15 were ever conducted.³⁹ SS-25 was never logged as part of this 1988 program or at any
16 other time.⁴⁰

17 SoCalGas's failure to follow its own 1988 plan to check the casing in 12 wells for
18 metal loss, violates Section 451. The significant metal loss found on five of the wells

³¹ If SED becomes aware of additional information that could modify SED's findings, SED reserves the right to supplement or modify its testimony with updated information as to the point in time when these leaks occurred, or take further actions as appropriate.

³² Blade Report at p. 2. The Blade Report mentions 13 such wells, but SED is identifying a separate violation for Well SS-25, the thirteenth well.

³³ Blade Report at pp. 2, 204.

³⁴ Blade Report at p. 2.

³⁵ Blade Report at p. 2.

³⁶ Blade Report at p. 2. To place the import of inspection logs in context, the Blade Report stated on page 183 that DOGGR later issued an Order (Order 1109) on March 4, 2016 that stated that "SoCalGas shall run a casing inspection log for all wells that were intended for future operations; otherwise the wells shall be plugged and abandoned."

³⁷ Blade Report at p. 2.

³⁸ Blade Report at p. 2.

³⁹ Blade Report at p. 219

⁴⁰ Blade Report at p. 3

1 identified in the 1988 memo presents a safety risk to the public and SoCalGas employees.
2 Given SoCalGas's failure to check these casings in response to its own August 1988
3 memo,⁴¹ twelve separate violations span from the end of August 1988 until October 23,
4 2015, the date of the incident.

5 As discussed below, SED identifies an independent violation for SS-25, which
6 was a thirteenth well identified in the 1988 memo that went unchecked for metal loss.

7 **c) SoCalGas Failed to Discover Specific Corrosion Problems**
8 **on Well SS-25**

9 Because SoCalGas did not attempt to understand causes of the leaks of 60 wells at
10 Aliso Canyon,⁴² and also did not follow its own 1988 plan to determine the condition of
11 the casing in SS-25,⁴³ it was unable to discover corrosion problems on Well SS-25, which
12 may have included what Blade found: that there had to be an environment that was more
13 dynamic, created by groundwater or other water source;⁴⁴ Blade found that the fluid
14 behind the 7-inch production casing had to be different than the original drilling fluid
15 since there was corrosion on the production casing OD;⁴⁵ that groundwater was the only
16 feasible source of water that could have occupied the space between⁴⁶ the 7-inch casing
17 and the 11-3/4-inch surface casing;⁴⁷ and, that groundwater is the only water source that
18 could have caused the 11-3/4-inch casing OD corrosion.⁴⁸ Blade found that well SS-25's
19 7-inch casing failure originated from 85% metal loss in the 7-inch steel casing wall due to

⁴¹ See Blade Report at p. 217. "In August 1988, an internal SoCalGas memo recommended that a casing inspection survey be run on 20 wells to "determine the mechanical condition of each well casing."

⁴² Blade Report at p. 4

⁴³ Blade Report at p. 3

⁴⁴ Blade Report at p. 88.

⁴⁵ Blade Report at p. 88.

⁴⁶ Blade describes this space between the seven inch and 11 3/4 inch surface casing using the term "annulus". (Blade Report at p. 88).

⁴⁷ Blade Report at p. 88

⁴⁸ Blade Report at p. 88

1 corrosion, which resulted in a 2-foot long axial rupture under an internal pressure of
2 2,791 psi in the space between (annulus) the 7-inch casing and the 2-7/8 inch tubing.⁴⁹

3 Blade identified a total of 58 through-wall-metal-loss holes in the 990-foot deep,
4 11-3/4-inch diameter steel surface casing walls of well SS-25.⁵⁰ Fifty of the steel surface
5 casing holes in SS-25 were identified at depths ranging between approximately 150 feet
6 and approximately 195 feet.⁵¹ The through-wall-metal-loss holes were identified using
7 various technologies, including caliper, UCI and HRVRT.⁵² Camera logging data were
8 consistent with the technology logging data, with photographs matching the sensory
9 logging tools' metal loss locations.⁵³

10 Based on Blade's RCA, a direct cause of the SS-25 incident was outside surface
11 corrosion of the 7-inch production casing.⁵⁴ The casing was corroding from the outside
12 as a result of contact with groundwater.⁵⁵ Groundwater and microbes—likely
13 methanogens, a form of Archaea⁵⁶—caused the corrosion.⁵⁷

14 Blade's analysis identified the corrosion by the nature of the corrosion surface,
15 (striated grooves with tunnels), which precludes other forms of corrosion, thus ruling out
16 many of the traditional corrosion mechanisms and concluding that microbial corrosion is
17 the likely mechanism.⁵⁸ For the 7-inch casing to have corroded, it must have been in
18 direct contact with an environment that allowed the corrosion mechanism to exist, and a
19 corrosion protection mechanism must have been absent.⁵⁹ The presence of bonded
20 cement outside of the 7-inch casing would have mitigated external corrosion. However,

⁴⁹ Blade Report at p. 80

⁵⁰ Blade Report at p. 119.

⁵¹ Blade Report at p. 119.

⁵² Blade Report at p. 119.

⁵³ Blade Report at p. 121

⁵⁴ Blade Report at p. 3

⁵⁵ Blade Report at p. 3.

⁵⁶ Methanogens are "metal eating" biological microorganisms.

⁵⁷ Blade Report at p. 3.

⁵⁸ Blade Report at p. 114

⁵⁹ Blade Report at p.215

1 there was no cement around the SS-25 7-inch well casing at 892 ft, because when the
2 well was originally drilled, the cement around the 7-inch casing was intentionally brought
3 up to 7,000 ft and not to surface.⁶⁰

4 In light of the extent of the corrosion on SS-25, and the resulting incident, SED
5 considers SoCalGas's failure to investigate the specific corrosion problems on Well SS-
6 25 its own separate violation of California Public Utilities Code Section 451. This
7 violation spans from August 31, 1988, the last date that the SoCalGas's 1988 memo
8 could have identified it, to October 23, 2015.

9 **SoCalGas did not have any form of risk assessment focused on**
10 **wellbore integrity management, including lack of assessment of**
11 **qualitative probability and consequences of production casing**
12 **leaks or failures.**⁶¹

13 SED finds multiple, separate violations of Section 451 related to SoCalGas's
14 failure to timely have an implement a Storage Integrity Management Program.

15 **a) SoCalGas Did Not Implement A Risk Assessment**
16 **Program or Wellbore Integrity Management Plan at Aliso**
17 **Canyon Storage Facility Prior to October 23, 2015**

18 SoCalGas's failure to implement any form of risk assessment program or wellbore
19 integrity management plan on the Aliso Canyon storage facility prior to October 23, 2015
20 is a separate violation of Section 451 for each day it failed to implement the risk
21 assessment program, beginning in 2009, the date at which it was advised by its Storage
22 Engineering Manager, Mr. James Mansdorfer, that it should have a well integrity
23 program.⁶²

24 According to Blade's Root Cause Analysis

25 Unlike robust transmission pipeline integrity and distribution
26 pipeline integrity programs, there was no such focus on well
27 integrity. This was also supported by SoCalGas's GRC

⁶⁰ Blade Report at p. 215

⁶¹ Blade Report at p. 4.

⁶² For discussion about the input from Mr. Mansdorfer regarding the well integrity program, see the next subsection. SED estimates December 31, 2009 to be the start date of this violation. If SED becomes aware of additional information that could modify SED's findings, SED may modify this testimony or take further actions as appropriate.

1 submission in 2012. . .SoCalGas was perhaps inadequately
2 resourced to manage Aliso Canyon prior to the 2015 incident,
3 but because detailed data on resourcing was not available, the
4 lack of resources was not identified as a root cause.⁶³

5 In SoCalGas's 2016 GRC proceeding, "SoCalGas had noted an increasing trend in
6 well integrity repairs, and without the [Storage Integrity Management Program],
7 operation would have continued in reactive mode, addressing mainly sudden and major
8 failures and service interruptions."⁶⁴

9 Prior to the incident of October 23, 2015, SoCalGas had recognized that its well
10 integrity program required significant changes, and had developed a plan, timeline, and
11 budget.⁶⁵ Considering the age of the wells and the quantity of casing leaks, the Root
12 Cause Analysis determined that a well integrity plan was necessary.⁶⁶

13 Also in SoCalGas's 2016 GRC, SoCalGas testified about the required operations
14 and maintenance expenses and capital investments for their underground storage facilities
15 and proposed a new six-year Storage Integrity Management Program (SIMP).⁶⁷ The
16 intent was to proactively identify and mitigate potential storage well safety and/or
17 integrity issues before they result in unsafe conditions for the public or employees.⁶⁸
18 SoCalGas had noted an increasing trend in well integrity repairs as part of the well repair
19 work.⁶⁹ As part of the well repair work from 2008 to 2013, SoCalGas explained that
20 mechanical damage and internal and external corrosion were identified in 15 wells with
21 the use of ultrasonic logs.⁷⁰ Also, the external corrosion had been observed at relatively

⁶³ Blade Report at p. 5.

⁶⁴ Blade Report at p. 182.

⁶⁵ Blade Report at p. 183.

⁶⁶ Blade Report at p. 183.

⁶⁷ Blade Report at p. 182.

⁶⁸ Blade Report at p.182.

⁶⁹ Blade Report at p.182.

⁷⁰ Blade Report at p.182.

1 shallow depths in the production casing.⁷¹ SoCalGas cited P-50A,⁷² where 400 psi was
2 observed in the casing annulus during routine weekly pressure surveillance in 2008; a
3 footnote provided additional information that a subsequent ultrasonic inspection revealed
4 external production casing corrosion from 450 to 1,050 ft.⁷³

5 Including P-50A, twelve wells in the SoCalGas's 2016 GRC testimony were Aliso
6 Canyon wells.⁷⁴

7 In the public records of 116 Aliso Canyon storage wells, Blade found production
8 casing inspection logs for 76 wells.⁷⁵ The 116 wells comprised the 114 wells listed under
9 the Comprehensive Safety Review, also known as SIMP, and 2 unique wells from the
10 2014 Testimony for the 2016 GRC.⁷⁶ The proposed SIMP program in SoCalGas's 2014
11 testimony included identifying threats and risk assessments for all wells.⁷⁷ SoCalGas
12 testified about the required operations and maintenance expenses and capital investments
13 for their underground storage facilities and proposed a new six-year SIMP.⁷⁸ The intent
14 was to "proactively identify and mitigate potential storage well safety and/or integrity
15 issues before they result in unsafe conditions for the public or employees."⁷⁹ The
16 objective of the log review was to determine to what degree the shallow external
17 corrosion found at SS-25 was an isolated event.⁸⁰ Out of the 76 wells with production
18 casing inspection logs, 27 of them had indications of shallow external corrosion on the
19 production casing.⁸¹

⁷¹ Blade Report at p.182.

⁷² According to Blade Report at p. 183, well P-50A was an Aliso Canyon well.

⁷³ Blade Report at p.182

⁷⁴ Blade Report at pp. 182-183.

⁷⁵ Blade Report at p. 183.

⁷⁶ Blade Report at p. 183.

⁷⁷ Blade Report at p. 183.

⁷⁸ Blade Report at p. 182.

⁷⁹ Blade Report at p. 182.

⁸⁰ Blade Report at p. 183.

⁸¹ Blade Report at p. 183.

1 In 1994, decades prior to SIMP, SoCalGas proposed to handle well integrity
2 management via certain types of surveys. In that year, SoCalGas proposed to DOGGR,
3 “. . . the most economical and effective method to monitor casing integrity of gas storage
4 wells is through the use of static temperature surveys.”⁸² DOGGR’s response to
5 SoCalGas’s proposal stated in part, “Therefore, the monitoring program and static
6 temperature surveys currently used by the Gas Company could be used to satisfy
7 compliance of the requirements for mechanical integrity found in this section [California
8 Code of Regulations Section 1724.10(k)(5)].”⁸³ However, the Root Cause Analysis
9 found that,

10 The casing leak in SS-25 showed that using temperature
11 surveys to confirm mechanical integrity of casing was
12 insufficient. . .⁸⁴ A temperature survey was run in SS-25 on
13 October 21, 2014, a year before the leak on October 23, 2015,
14 and showed no temperature anomalies.⁸⁵

15 Noise and temperature surveys are used to identify leaks, but
16 the sensitivity of the instruments is limited.⁸⁶ If no leak is
17 detected, noise and temperature data provide no indication of
18 future integrity problems.⁸⁷ Noise and temperature logs are
19 trailing indicators; and by no means sufficient to manage well
20 integrity.⁸⁸ Alternatively, casing inspection can identify
21 defects that may be growing with time and can be used to
22 monitor integrity deterioration.⁸⁹

23 Numerous temperature, noise, and pressure surveys were run
24 in SS-25 between the years of 1974 and 2014, and no major
25 anomalies were found indicating fluid migration.⁹⁰

⁸² Blade Report at p.198.

⁸³ Blade Report at p. 198.

⁸⁴ Blade Report at p.198.

⁸⁵ Blade Report at p. 198.

⁸⁶ Blade Report at p.198.

⁸⁷ Blade Report at p. 198.

⁸⁸ Blade Report at p. 198.

⁸⁹ Blade Report at p.198.

⁹⁰ Blade Report at p. 198.

1 SoCalGas's failure to implement any form of risk assessment program or wellbore
2 integrity management plan on the Aliso Canyon storage facility prior to October 23,
3 2015, beginning in 2009,⁹¹ and continuing through October 23, 2015, constitutes a
4 separate violation of Section 451 for each day it failed to implement the risk assessment
5 program.

6 **b) SoCalGas's Failure to Implement A Risk Assessment**
7 **Program or Wellbore Integrity Management Plan at Aliso**
8 **Canyon Storage Facility Prior to October 23, 2015**
9 **Resulted in the Failure to Detect Corrosion on the Well**
10 **SS-25 Seven Inch Casing Prior to October 23, 2015**

11 Corrosion was not detected on SS-25 because the seven inch casing wall thickness
12 on the SS-25 had never been inspected.⁹² Various tools can be run in a well with wireline
13 to measure well thickness along the entire length of a casing or tubing string.⁹³ These
14 logs were not run in the seven inch casing of well SS-25, in part because no risk
15 assessment was performed.⁹⁴

16 SED finds that the failure to detect corrosion on SS-25 that resulted in part from
17 SoCalGas's failure to perform a risk assessment on Aliso Canyon is a separate violation
18 of Section 451, beginning December 31, 2009, and continuing through October 23,
19 2015.^{95 96}

⁹¹ Section III.B.2.c discusses that SoCalGas's Storage Engineering Manager recommended to SoCalGas that it perform a risk assessment review in 2009, but that SoCalGas failed to do so. This is the basis for the start date of the violation. SED uses December 31, 2009 as the current beginning date of this violation. If SED becomes aware of additional information that could modify SED's testimony, SED may modify it or take further actions, as appropriate.

⁹² Blade Report at p. 216.

⁹³ Blade Report at p. 216.

⁹⁴ Blade Report at p.216

⁹⁵ As discussed in Section III.B.2.c below, SoCalGas failed to implement a risk assessment review that had been recommended by its Storage Engineering Manager, Mr. James Mansdorfer, in 2009. This is the basis for the beginning of the violation.

⁹⁶ If SED becomes aware of additional information that could modify SED's testimony, SED may modify it or take further actions, as appropriate.

1 c) **SoCalGas Did Not Start a Storage Integrity Management**
2 **Program in 2009, Even Though It Was Recommended by**
3 **Its Storage Engineering Manager at that Time, Because**
4 **They Could Not Yet Collect It in Rates**

5 SoCalGas's storage engineering manager in 2009, James Mansdorfer,
6 recommended a storage well integrity program to SoCalGas at that time.⁹⁷ In
7 recommending that storage well integrity program, he stated, "a structured program
8 where [SoCalGas has] a schedule that will eventually result in a casing inspection and
9 pressure test for every storage well."⁹⁸ He recommended to his direct supervisor that the
10 storage integrity program include putting a rig on each of the storage wells,⁹⁹ running
11 casing and inspection logs,¹⁰⁰ and pressure testing the casing.¹⁰¹

12 Also, according to Mr. Mansdorfer, SoCalGas knew a storage well integrity
13 program was needed in 2009, but had not started it because the company could not yet
14 collect the cost of the program in rates.¹⁰²

15 Eight years prior to the October 23, 2015 incident , SoCalGas had recognized that
16 its well management program required significant changes.¹⁰³ In the SoCalGas 2007
17 testimony for the 2008 General Rate Case (GRC), costs and details were outlined related
18 to reservoir engineering studies, additional personnel, technological advances, and well
19 expenses.¹⁰⁴ SoCalGas claimed that over a 15-year period, the number of gas storage
20 specialists reduced from 10 to 4 for unspecified reasons, and the company "experienced a
21 significant decline in its ability to assess the performance of individual wells due to the

⁹⁷ Tr. Mansdorfer, September 13, 2018 at pp. 9:7 - 10:11.

⁹⁸ Tr. Mansdorfer, September 13, 2018 at pp. 124:28 - 125:14.

⁹⁹ Tr. Mansdorfer, September 13, 2018 at p. 125:19-23.

¹⁰⁰ Tr. Mansdorfer, September 13, 2018 at p. 125:24-26.

¹⁰¹ Tr. Mansdorfer, September 13, 2018 at p. 125:27-28.

¹⁰² Tr. Mansdorfer, September 13, 2018 at p. 126:25 - 127:23.

¹⁰³ Blade Report at p. 183.

¹⁰⁴ Blade Report at pp. 5, 182.

1 lack of recent data.”¹⁰⁵ In 2007, SoCalGas requested two additional specialists.¹⁰⁶
2 Unlike SoCalGas’s robust transmission pipeline integrity and distribution pipeline
3 integrity programs, there was no such focus on well integrity.¹⁰⁷ This was also supported
4 by the SoCalGas GRC submission in 2012.¹⁰⁸

5 SoCalGas’s failure to start the well integrity program in 2009 because it could not
6 yet collect the cost of the program in rates constituted its own separate violation of
7 Section 451. This violation began on December 31, 2009 and continued until October
8 23, 2015.¹⁰⁹

9 **SoCalGas did not have a dual mechanical barrier system in the**
10 **wellbore of SS-25, instead leaving the 7-inch production casing**
11 **as the primary barrier to the gas.**

12 In identifying the lack of a dual barrier system for SS-25, Blade stated,

13 SS-25 was operated so that gas injection and withdrawal was
14 done through the 2 7/8 in. tubing and the 7 in. casing x 2 7/8
15 in. tubing annulus. As such, the 7 in. casing acted as a single
16 barrier and when it failed, there was nothing behind it to
17 contain the wellbore pressure and fluids.¹¹⁰

18 To further illustrate the lack of a dual barrier in the case of SS-25, Blade added,

19 According to the Blade Report,

20 SS-25 was drilled as a Standard Sesnon reservoir oil well in
21 1954. After the oil reservoir was considered depleted, SS-25
22 was converted to a gas storage well in 1973. Operationally,
23 there were some key differences between the use of SS-25 in
24 oil production mode and in gas storage mode. As an oil well,
25 the oil was produced through a inch tubing string; the primary
26 mechanical barrier to the oil was the tubing, and the
27 secondary one was the casing. As a gas storage well, the gas
28 was injected and withdrawn through the tubing and the

¹⁰⁵ Blade Report at pp. 5, 182.

¹⁰⁶ Blade Report at p. 182.

¹⁰⁷ Blade Report at p. 5.

¹⁰⁸ Blade Report at p. 5.

¹⁰⁹ SED is using December 31, 2009, as the current beginning date, and October 23, 2015, as the current end date of this violation. If SED becomes aware of additional information that could modify SED’s testimony, SED may modify it or take further actions, as appropriate.

¹¹⁰ Blade Report at p. 233, Solution 9: Tubing Packer Completion-Dual Barrier System.

1 casing, making the 7-inch casing the primary barrier for the
2 gas during gas storage operations. .¹¹¹

3 Pressure tests were conducted on the SS-25 casing in 1973
4 during the well's conversion from oil production to gas
5 storage.¹¹² The well's integrity was monitored using yearly
6 temperature logs and occasional noise logs.¹¹³ If a leak in the
7 casing had occurred, then the casing would have locally
8 cooled, and consequently the temperature would have
9 deviated at the leak location.¹¹⁴ The SS-25 temperature and
10 noise logs had never shown an anomaly related to casing
11 integrity.¹¹⁵ Pressure measurements, which were collected at
12 SS-25 weekly, had not indicated a leak or failure prior to the
13 incident. Well integrity issues went undetected until the leak
14 event of October 23, 2015.¹¹⁶

15 Also as noted by SoCalGas's Storage Engineering Manager, James Mansdorfer, in
16 2009,

17 Back in the 1970's our predecessors were concerned about
18 this enough to install subsurface safety valves in all wells at
19 Aliso. Unfortunately, at the time the technology was not up
20 to the challenge and all of the valves failed and were
21 subsequently removed. However due to deepwater high flow
22 rate wells the technology is now available to install deep set
23 valves that will withstand high flow rates. We have one of
24 these in Miller 4. We could leave the wells in annular flow
25 configuration so we don't have the cost, problems and
26 deliverability loss associated with conversion to tubing
27 flow.¹¹⁷

28 With regards to whether subsurface safety valves could work on both tubing and
29 casing at Aliso Canyon, Mr. Mansdorfer from 2009 later clarified under oath as follows:

30 Q: Okay. Subsurface safety valves very quickly. What is
31 your understanding as to whether subsurface safety valves,

¹¹¹ Blade Report at p. 2.

¹¹² Blade Report at p. 2.

¹¹³ Blade Report at p. 2.

¹¹⁴ Blade Report, p. 2.

¹¹⁵ Blade Report, p. 2.

¹¹⁶ Blade Report, p. 2.

¹¹⁷ Thursday, April 23, 2009 2:12 PM, Mansdorfer to Weibel email: 11906016_SCG_CALADVOCATES_0017314.

1 can they work for both tubing and casing of a well or merely
2 tubing?

3 A: Well, there's different styles. PG&E has ones that work
4 on both tubing and casing. I think they're kind of
5 troublesome but most of them, well, almost all of them are set
6 up to work on tubing only.

7 Q: I see. And that includes for deepset?

8 A: Right. It would have to flow through a packer and to the
9 tubing. And then if you wanted to flow in the annulus, it
10 would have to flow out through ports and up the annulus.¹¹⁸

11 On April 23, 2009, Mr. Mansdorfer stated that more than 100 storage wells were
12 set up for annular flow in the same fashion that Blade noted SS-25 was operated. In his
13 words, "At Aliso Canyon we have over 100 storage wells that are set up for annular flow
14 with up to 3150 psi on the casing. A few of these wells are under 10 years old, but the
15 majority are from 35 to 70 years old."¹¹⁹

16 The Aliso Canyon storage wells had numerous casing leaks.¹²⁰ Blade reviewed
17 124 gas storage wells and identified 63 casing leaks, 29 tight spots, 4 parted casings, and
18 3 other types of failures.¹²¹ Casing leaks include both connection leaks and pipe body
19 leaks.¹²² Based on the data available to blade, no details regarding the nature of cause of
20 these leaks and failures were available because no failure analyses were done.¹²³ Forty
21 percent of the gas storage wells reviewed by Blade had casing failures with an average of
22 two casing failures per well.¹²⁴ The FF-34A well file mentioned a study of the possible

¹¹⁸ Tr. Mansdorfer, September 13, 2018 at pp. 143:21 – 144:9. If SED becomes aware of additional information that could modify SED's testimony, SED may modify it or take further actions, as appropriate. In particular, SED may propound further discovery to inform whether SoCalGas could have successfully used subsurface safety valves on both the tubing and the casing on wells in the Aliso Canyon Natural Gas Storage facility prior to October 23, 2015. If it turns out that SoCalGas could have done so, SED reserves the right to assert additional violations of California Public Utilities Code Section 451 related to this matter.

¹¹⁹ Thursday, April 23, 2009 2:12 PM, Mansdorfer to Weibel email; ref-VLB-003, 2009.0423. Aliso Testimony. JMansdorfer at p. 1.

¹²⁰ Blade Report at p. 2.

¹²¹ Blade Report at pp. 2, 203.

¹²² Blade Report at p. 203.

¹²³ Blade Report at p. 2.

¹²⁴ Blade Report at pp. 2, 203. This was 99 failures in 49 wells (See Blade Report at p. 203).

1 external casing corrosion problems in the southeastern portion of the field, but Blade was
2 not able to locate any documentation related to this study.¹²⁵

3 In addition, two Aliso Canyon wells had underground blowouts from casing leaks:
4 Frew-3 in 1984 and FF-34A in 1990.¹²⁶ These wells were successfully killed by pumping
5 fluid down the tubing, and the consequences of a larger leak or a near-surface casing
6 rupture were not anticipated until the SS-25 event.¹²⁷

7 As noted in Section B.1.b above, SoCalGas had a two-year plan in 1988 to
8 determine the mechanical condition of the casing in 20 wells originally completed in the
9 1940s and 1950s, but did not completely follow it.¹²⁸

10 Blade reviewed SS-25 noise, temperature, and pressure surveys before the incident
11 of October 23, 2015.¹²⁹ There were not temperature, pressure, or noise anomalies in the
12 surveys that indicated a preexisting casing failure.¹³⁰ Additionally, there were no
13 physical observations from well inspections and weekly pressure measurements that
14 indicated an existing problem.¹³¹ Blade's interpretation is that SoCalGas complied with
15 the monitoring components of the Operations Standard titled Gas Inventory –
16 Monitoring, Verification and Reporting.¹³²

17 The catastrophic SS-25 casing leak showed that using temperature surveys to
18 confirm mechanical integrity of casing was a flawed concept.¹³³ The concept assumed
19 that leaks would not be catastrophic, would cause a cooling anomaly, and would be
20 detected in time to allow the well to be killed quickly and safely.¹³⁴ A temperature

¹²⁵ Blade Report at p. 2.

¹²⁶ Blade Report at p. 2.

¹²⁷ Blade Report at p. 2.

¹²⁸ Blade Report at p. 2.

¹²⁹ Blade Report at p. 202.

¹³⁰ Blade Report at p. 202.

¹³¹ Blade Report at p. 202.

¹³² Blade Report at p. 202.

¹³³ Blade Report at p. 202.

¹³⁴ Blade Report at p. 202.

1 survey was run in SS-25 on October 21, 2014, a year before the leak on October 23,
2 2015, and showed no temperature anomalies.¹³⁵

3 Allowing an annual temperature survey to meet the requirements of mechanical
4 integrity test is insufficient for several reasons:¹³⁶

- 5 • A leak and cooling must exist to develop a temperature
6 anomaly.¹³⁷
- 7 • Lack of an anomaly does not provide any data regarding
8 the future integrity of the casing or remaining wall
9 thickness.¹³⁸
- 10 • Temperature change must be within the sensitivity of the
11 tool.¹³⁹
- 12 • Interpretation of the survey is subjective.¹⁴⁰

13 A large number of production casing leaks and parted casings have occurred
14 throughout the history of the Aliso Canyon field, with a risk of gas leaks and safety and
15 environmental repercussions.¹⁴¹ In spite of the possible consequences, no data were
16 provided to Blade to demonstrate that measures were taken to understand the root causes
17 of the casing and well failures.¹⁴² The wells files and data made available to Blade are
18 mostly void of analyses of the causes of failures.¹⁴³ An interoffice memo related to
19 FF-34A stated that “The possible regional external casing corrosion problem in the
20 southeastern portion of the field that was going to be further studied and a report issues”;
21 however, Blade was not able to locate any documentation regarding this study.¹⁴⁴

¹³⁵ Blade Report at p. 202.
¹³⁶ Blade Report at p. 203.
¹³⁷ Blade Report at p. 203.
¹³⁸ Blade Report at p. 203.
¹³⁹ Blade Report at p. 203.
¹⁴⁰ Blade Report at p. 203.
¹⁴¹ Blade Report at p. 203.
¹⁴² Blade Report at p. 203.
¹⁴³ Blade Report at p. 203.
¹⁴⁴ Blade Report at p. 203.

1 SoCalGas has a Company Operations Standard (191.01) for the Investigation of
2 Accidents and Pipeline Failures, but a complementary standard for the investigation of a
3 well failure had not been identified to Blade.¹⁴⁵ This implied that more attention was
4 paid to surface equipment and asset failures than to well and downhole failures.¹⁴⁶

5 As part of interoffice correspondence, SoCalGas made a recommendation in 1988
6 to run casing inspection logs in the 20 wells that were of concern at the time, and the
7 opportunity to inspect the casing in SS-25 was missed. It is not possible to determine
8 what an inspection of the SS-25 casing would have shown in 1988, but it is possible that
9 the corrosion was present and detectable, and steps could have been taken to avoid the
10 leak in 2015.¹⁴⁷ SoCalGas logged some of the 13 remaining wells starting in 2007,
11 resulting in a gap from 1990 to 2007 when no inspection logs were run in the 20 wells,
12 according to the available well records.¹⁴⁸

13 SoCalGas logged the High Priority wells and found significant penetration.¹⁴⁹ No
14 documentation was found that explained why the remaining wells were not inspected as
15 recommended in 1988.¹⁵⁰ Blade inquired if SS-25 was inspected based on the 1988
16 recommendation because it was on the list of 20 wells.¹⁵¹ SoCalGas responded to a
17 Blade information request dated December 18, 2018, that the high priority wells were
18 logged, and SS-25 was not inspected because the Vertilog technology was less effective
19 at identifying casing leaks than the well diagnostic tests that SoCalGas routinely
20 performed on its underground gas storage wells.¹⁵² However, the objective of the 1988

¹⁴⁵ Blade Report at p. 203.

¹⁴⁶ Blade Report at p. 203.

¹⁴⁷ Blade Report at p. 204.

¹⁴⁸ Blade Report at p. 204.

¹⁴⁹ Blade Report at p. 204.

¹⁵⁰ Blade Report at p. 204.

¹⁵¹ Blade Report at p. 204-205.

¹⁵² Blade Report at p. 205.

1 inspections was to determine the mechanical condition of the casing and not to identify
2 casing leaks.¹⁵³

3 There were 76 of 116 wells that had production casing inspection logs available,
4 of which, 27 wells showed indications of shallow external corrosion on the production
5 casing.¹⁵⁴ In almost all of these 27 wells, the external corrosion was below the depth of
6 the surface casing shoe.¹⁵⁵ There were two exceptions, F-4 and P-50A.¹⁵⁶ The shallow
7 corrosion in P-50A was found above the shoe and abruptly stops at the depth of the
8 casing shoe.¹⁵⁷

9 Although no well was found with the exact placement and pattern of corrosion as
10 that of SS-25, Blade concluded that shallow corrosion was a common event that was
11 found field wide, and close to the surface casing shoe.¹⁵⁸ Shallow casing leaks occurred
12 in a number of wells.¹⁵⁹ Blade found 10 shallow casing leaks in a review of 116 wells.¹⁶⁰
13 Blade interpreted that three of these shallow casing leaks could be attributed to shallow
14 corrosion; three were not.¹⁶¹ There was not enough information to determine if the
15 remaining shallow casing leaks were corrosion related.¹⁶²

16 Surface casing corrosion was identified in several wells where casing inspection
17 logs were run as part of the P&A (plug and abandonment) operations.¹⁶³ SS-25's surface
18 casing had the worst condition; logs showed multiple through-wall holes in the 11 ¾ in.
19 casing from approximately 134 to 300 ft.¹⁶⁴ The holes in the surface casing likely

¹⁵³ Blade Report at p. 205.

¹⁵⁴ Blade Report at p. 205.

¹⁵⁵ Blade Report at p. 205.

¹⁵⁶ Blade Report at p. 205.

¹⁵⁷ Blade Report at p. 205.

¹⁵⁸ Blade Report at p. 205.

¹⁵⁹ Blade Report at p. 205.

¹⁶⁰ Blade Report at p. 205.

¹⁶¹ Blade Report at p. 205.

¹⁶² Blade Report at p. 205.

¹⁶³ Blade Report at p. 205.

¹⁶⁴ Blade Report at p. 205.

1 contributed to the 7-inch production casing corrosion and allowed ground water and
2 oxygen to enter the 11 ¾ inch x seven-inch annulus.¹⁶⁵

3 SED finds that SoCalGas violated Section 451 by operating well SS-25 without a
4 backup mechanical barrier to the 7-inch production casing. In August 1988, an internal
5 SoCalGas memo recommended that a casing inspection survey be run on 20 wells to
6 “determine the mechanical condition of each well casing.”¹⁶⁶ Given SoCalGas’s failure
7 to inspect the casing of SS-25 in response to its own August 1988 memo,¹⁶⁷ this violation
8 spans from at the latest the end of August 1988 until October 23, 2015.¹⁶⁸

9 **SoCalGas did not have internal policies that required inspection**
10 **and measurement of the wall thickness of wellbores at Aliso.**¹⁶⁹
11 **Instead, SoCalGas used techniques that detected and fixed leaks**
12 **only after an event occurred.**¹⁷⁰

13 SoCalGas had no internal policies on wall thickness inspections because the
14 company assumed that regulatory compliance was being adhered to by running annual
15 temperature surveys in accordance with the Aliso Canyon Monitoring Plan and the
16 project approval letter dated 1989 requiring an annual mechanical integrity test (MIT).¹⁷¹
17 The MIT monitoring system did find casing leaks on other wells in the field, which were
18 successfully repaired or remediated.¹⁷² But, no failure analysis or risk assessment was

¹⁶⁵ Blade Report at p. 205.

¹⁶⁶ Blade Report at p. 217.

¹⁶⁷ See Blade Report at p. 217.

¹⁶⁸ If SED becomes aware of additional information that could modify SED’s testimony, SED may modify it or take further actions, as appropriate. In particular, SED may propound further discovery to inform whether SoCalGas could have successfully used subsurface safety valves on both the tubing and the casing on wells in the Aliso Canyon Natural Gas Storage facility prior to October 23, 2015. If it turns out that SoCalGas could have done so, SED reserves the right to assert additional violations of California Public Utilities Code Section 451 related to this matter.

¹⁶⁹ Blade Report at p. 5.

¹⁷⁰ Blade Report at p. 5.

¹⁷¹ Blade Report at p. 217. According to the Blade Report at pp. 197-198 A mechanical integrity test (MIT) must be performed on all injection wells to ensure the injected fluid is confined to the approved zones. The MIT consists of two parts. 1. Prior to commencing injection operations, each injection well must pass a pressure test of the casing-tubing annulus to determine the absence of leaks. Thereafter, the annulus of each well must be tested at least once every five years. 2. The second test of a two-part MIT shall demonstrate that there is no fluid migration behind the casing, tubing, or packer.

¹⁷² Blade Report at p. 217.

1 ever done on previous wells that had leaks or corrosion.¹⁷³ In addition, there had not
2 been an event of similar severity to what happened on SS-25.¹⁷⁴ Further, since no formal
3 risk assessment was conducted regarding well integrity, wall thickness inspection was not
4 identified as a monitoring technique.¹⁷⁵

5 A wall thickness inspection provides a leading indicator of possible casing
6 integrity issues.¹⁷⁶ The noise and temperature logs results are trailing indicators because
7 the leak has to already have happened to be detected.¹⁷⁷ Seven of the 20 wells
8 recommended for a casing wall thickness inspection in the SoCalGas 1988 memo were
9 inspected and many of them had outside diameter (OD) metal loss indications.¹⁷⁸ There
10 was no follow-up investigation of these anomalies.¹⁷⁹ Further, there was no investigation
11 of why these wells exhibited OD corrosion and why the remaining thirteen wells did not
12 require further analyses (the remaining thirteen wells had been ranked as medium and
13 low priority).¹⁸⁰

14 SoCalGas ran annual temperature surveys and periodic noise logs in SS-25 from
15 1974 to 2014, and no anomalies were found.¹⁸¹ However, this type of monitoring
16 program is not capable of detecting casing metal loss, corrosion or the growth of
17 corrosion over time.¹⁸² Temperature and noise surveys do not measure wall thickness;
18 they will only detect a leak and are consequently after-the-fact, reactive techniques.¹⁸³

19 As discussed in Section B.1.b, an internal SoCalGas memo issued in August 1988
20 recommended that a casing inspection survey be run on 20 wells to “determine the

¹⁷³ Blade Report at p. 217.

¹⁷⁴ Blade Report at p. 217.

¹⁷⁵ Blade Report at p. 217.

¹⁷⁶ Blade Report at p. 218.

¹⁷⁷ Blade Report at p. 218.

¹⁷⁸ Blade Report at p. 218.

¹⁷⁹ Blade Report at p. 218.

¹⁸⁰ Blade Report at p. 218.

¹⁸¹ Blade Report at p. 216.

¹⁸² Blade Report at p. 216.

¹⁸³ Blade Report at p. 216.

1 mechanical condition of each well casing.¹⁸⁴ Despite the number of casing failures that
2 had occurred in the field, no failure analysis or subsequent risk assessment was done that
3 may have led to an awareness that corrosion was a potential problem.¹⁸⁵ In addition,
4 there had not been an event of similar severity to what happened on SS-25.¹⁸⁶ Further,
5 since no formal risk assessment was conducted regarding well integrity, wall thickness
6 inspection was not identified as a monitoring technique.¹⁸⁷ Section B.1.b discusses in
7 more detail the number of casing failures that had occurred at Aliso, and the failure to
8 follow each of the recommendations in the 1988 memo.¹⁸⁸

9 Although there were no regulatory requirements for wall thickness measurements
10 to be done,¹⁸⁹ SoCalGas operated its Aliso Canyon storage facility without internal
11 policies that required well casing wall thickness inspection and measurement in violation
12 of Section 451. The span of this violation extends from the issuance of the memo in
13 August 1988 to October 23, 2015, the date of the incident.

14 **SoCalGas did not have a well specific, well control plan that**
15 **considered transient kill modeling or well deliverability. There**
16 **was not quantitative understanding of well deliverability,**
17 **although data were available, and well-established industry**
18 **practices existed for such analysis.**

19 With regards to Relief Well 2, Well SS-25A, and SS-25B, SoCalGas did not have
20 kill programs as of February 4, 2016.¹⁹⁰

21 Between October 24 and December 22, 2015, seven kill operations were attempted
22 to bring wells-25 under control and to stop the leak.¹⁹¹ The date and a brief description of

¹⁸⁴ Blade Report at p. 217.

¹⁸⁵ Blade Report at p. 217.

¹⁸⁶ Blade Report at p. 217.

¹⁸⁷ Blade Report at p. 217.

¹⁸⁸ See also Blade Report at p. 218.

¹⁸⁹ Blade Report at p. 217.

¹⁹⁰ Email from Brett Lane to Jimmie Cho et al., entitled "Randy Request" AC_CPUC_SED_DR_16_0043578.
"Jimmie: Tried to make this easy for you. Attached is the latest draft of the intercept/kill procedure for relief well 1
to SS-25 and the dynamic kill analysis. I have also included the last 5 ranging run reports. We do not have a
dynamic kill program developed yet for Relief well 2. We do not have kill programs for SS25A or 25B."

¹⁹¹ Blade Report at p. 144.

1 each kill attempt are provided in Table 2, provided below.¹⁹² The first kill operation was
2 managed by SoCalGas and the remaining six kill operations were managed by Boots and
3 Coots, a well-control company contracted by SoCalGas.¹⁹³ None of the attempts were
4 successful and each attempt made the surface conditions worse.¹⁹⁴ Kill attempt number
5 seven appeared to be close to killing the well, but it was terminated because of
6 undesirable movement of the wellhead and pump lines that broke during the job.¹⁹⁵

7 In designing a kill operation, the objective is to place a fluid of sufficient density
8 into the wellbore such that the hydrostatic pressure exerted by this fluid is higher than the
9 pressure of the flowing gas.¹⁹⁶ The two primary design variables are the fluid density and
10 pump rate.¹⁹⁷ The primary constraint is that the pressure rating of the surface wellhead
11 equipment must not be exceeded.¹⁹⁸ In general, the lower fluid densities require higher
12 pump rates and result in higher pressures at the wellhead.¹⁹⁹

13 Blade reviewed all the available data and concluded that no transient modeling
14 was done when designing kill attempts one through six.²⁰⁰ Based on the data reviewed by
15 Blade, the well-control company appeared to have designed the kill attempts solely by
16 calculating a kill fluid density that was higher than the static bottom hole pressure.²⁰¹
17 Kill operations where a fluid is being pumped into a well while the gas is escaping at a
18 high rate requires a detailed transient model to define the operational parameters.²⁰²

¹⁹² Table 2 below is a copy of Table 18 of the Blade Report.

¹⁹³ Blade Report at p. 144.

¹⁹⁴ Blade Report at p. 144.

¹⁹⁵ Blade Report at p. 229.

¹⁹⁶ Blade Report at p. 144.

¹⁹⁷ Blade Report at p. 144.

¹⁹⁸ Blade Report at p. 144. In this case, the surface equipment was rated to 5,000 psi.

¹⁹⁹ Blade Report at p. 144.

²⁰⁰ Blade Report at p. 4.

²⁰¹ Blade Report at p. 3.

²⁰² Blade Report at p. 4.

1 Mr. Mansdorfer identified calculations for flow rate and mud weight that may
2 have successfully killed the well also, which was based on information from the website
3 of the Division of Oil, Gas, and Geothermal Resources (DOGGR).²⁰³

4 Blade conducted detailed modeling and used the more accurate estimate of flow
5 rate and concluded that 12 pounds per gallon (ppg) fluid weight or higher at pump rates
6 of 10 barrels per minute (bpm) or higher would have successfully controlled the well as
7 early as November 13 or 14, 2015.²⁰⁴ Instead, a variation of the same kill attempt design
8 with fluid densities of around 9.4 ppg and flow rates of around 5 to 13 bpm were utilized
9 for kill attempts two through six.²⁰⁵

10 Meanwhile, the well site deteriorated with the continued flow of gas.²⁰⁶ Blade
11 reviewed all the available data and concluded that no transient modeling was done when
12 designing these kill attempts, contributing to the lack of success in the kill attempts.²⁰⁷
13 The data indicated that the well flow rate was being significantly underestimated.²⁰⁸

14 At the time of the first kill attempt, the estimate leak rate was 93 MMscf/D.²⁰⁹
15 Blade's analysis indicated that the 10 ppg fluid was not dense enough to kill the well at
16 realistic pumping rates.²¹⁰ The well could have been killed by pumping 12 ppg fluid at
17 10 bpm or a 15 ppg fluid at 7 bpm.²¹¹ The first well kill attempt was a reasonable
18 response because the extent of the failure in SS-25 was unknown.²¹² Similar well kill
19 operations had been carried out in the past on wells with casing leaks, namely Frew 3 in
20 1984 and Fernando Fee (FF) 34A in 1990.²¹³ The two wells were killed successfully by

²⁰³ Tr. Mansdorfer, September 13, 2018 at pp. 81:20 – 83:9.

²⁰⁴ Blade Report at p. 4.

²⁰⁵ Blade Report at p. 4.

²⁰⁶ Blade Report at p. 4.

²⁰⁷ Blade Report at p. 4.

²⁰⁸ Blade Report at p. 4.

²⁰⁹ Blade Report at p. 148.

²¹⁰ Blade Report at p. 148.

²¹¹ Blade Report at p. 148.

²¹² Blade Report at p. 148.

²¹³ Blade Report at p. 148.

1 pumping fluid down the tubing.²¹⁴ Gas broaching to surface from cracks in the ground
2 following kill attempt #1 indicated that SS-25 had serious problems and that a shallow
3 casing leak likely existed.²¹⁵

4 The second through sixth well kill attempts failed because the kill fluids used were
5 not dense enough to kill the well.²¹⁶ For example, on November 13, 2015, the well-
6 control company executed the second well kill attempt, which was also unsuccessful.²¹⁷
7 During the second well kill attempt, the Blade estimated flow rate was 83 MMscf/D.²¹⁸
8 The 9.4 ppg kill density fluid could not kill this well;²¹⁹ however, 12 ppg at a flow rate of
9 9 to 10 bbl/min would have gotten the well under control.²²⁰ Also, the well could have
10 been killed by pumping 15 ppg fluid at 6 bpm.²²¹ Blade's analyses assume that kill fluids
11 would have been pumped down the tubing; it would have been impossible to kill SS-25
12 by pumping down the seven inch casing.²²²

13 Between November 14 and November 25, 2015, the well-control company
14 executed four other kill attempts.²²³ All four kill attempts failed, and the SS-25 surface
15 conditions worsened.²²⁴ All four kill attempts were similar in design.²²⁵ The main
16 components of the kill fluids were 9.4 ppg CaCl₂ fluid for the third and fourth well kill
17 attempts and fresh water (estimated 8.34 ppg density) for the fifth and sixth well kill
18 attempts.²²⁶ The estimated gas leak rates were 81 MMscf/D for the third and fourth well

²¹⁴ Blade Report at p. 148.

²¹⁵ Blade Report at p. 148.

²¹⁶ Blade Report at p. 159.

²¹⁷ Blade Report at p. 148.

²¹⁸ Blade Report at pp. 149, 228.

²¹⁹ Blade Report at pp. 149, 229.

²²⁰ Blade Report at pp. 149, 229.

²²¹ Blade Report at p. 149.

²²² Blade Report at p. 149.

²²³ Blade Report at p. 150.

²²⁴ Blade Report at p. 150.

²²⁵ Blade Report at p. 150.

²²⁶ Blade Report at p. 150.

1 kill attempts and 78 MMscf/D for the fifth and sixth well kill attempts.²²⁷ Blade analyses
2 indicate that the fluid densities were not high enough to kill the well at realistic pump
3 rates for any of the four kill attempts.²²⁸ The well could have been killed with either 12
4 ppg or 15 ppg kill fluid at realistic pump rates (6-8 bpm).²²⁹

5 Blade indicates that at the time of the fifth kill attempt, the well was flowing at 78
6 MMscf/D. Blade believes that 12.0 ppg fluid pumped at 8 bpm or 15.0 ppg fluid at 6
7 bpm would have also stopped the gas flow.²³⁰ The fluid would have tended to maintain a
8 stable fluid column because of the damage to the reservoir permeability, while clear
9 water or clear brine would not have remained stable because of fluid loss into the
10 permeable reservoir.²³¹

11 The sixth well kill attempt was a near repeat of the fifth well kill attempt, except
12 that the 35 bbl barite pill was replaced with a 100 bbl 9.4 ppg LCM pill, and a higher
13 pump rate was applied to the kill.²³² The sixth attempt appeared to have killed the well,
14 but fluid loss into the formation kept the annular fluid column from stabilizing.²³³ It is
15 probable that continued pumping from the surface might have kept up with the fluid loss,
16 but surface plumbing failures prevented the well from being kept filled.²³⁴ The use of
17 fresh water and clear brine contributed to the attempt's failure because of fluid loss into
18 the formation and loss of hydrostatic pressure, which allowed the well to flow after the
19 kill attempt.²³⁵

²²⁷ Blade Report at p. 150.

²²⁸ Blade Report at p. 150.

²²⁹ Blade Report at p. 150.

²³⁰ Blade Report at p. 151.

²³¹ Blade Report at p. 151.

²³² Blade Report at p. 151.

²³³ Blade Report at p. 151.

²³⁴ Blade Report at p. 151.

²³⁵ Blade Report at p. 151.

1 At this point, the wellhead and surface casing were structurally unstable.²³⁶ Gas
2 and fluid flow around the surface location removed enough soil and formation to allow
3 considerable oscillation of the wellhead.²³⁷

4 The final well kill attempt was executed by the well-control company on
5 December 22, 2015.²³⁸ After installing guy wires to reduce wellhead oscillations, the
6 pump job for this kill attempt consisted of pumping 15.1 ppg water based mud (WBM),
7 with LCM, at a rate of five bpm.²³⁹ (Reports are inconsistent—the actual rate may have
8 been 5.8 bpm.)²⁴⁰ After pumping 300 bbl, the injection rate was reduced to 0.5 bpm for
9 15 minutes.²⁴¹ Pumping was terminated due to rocking of the wellhead and a subsequent
10 failure of the injection connection.²⁴² At 10:30 AM, the well was just about to be killed,
11 although premature shutdown of the pumps resulted in the FBHP decreasing and the
12 influx rate increasing.²⁴³ Pumping needed to continue for some time after the well had
13 seemed to have been killed to ensure that the well had been effectively killed.²⁴⁴ This did
14 not happen in the field because the pumps were shut down early.²⁴⁵ Blade’s analysis
15 confirms that the well should have been killed with either 12 ppg fluid pumped at 6 bpm
16 or 15 ppg fluid pumped at 5 bpm.²⁴⁶

17 The seventh (last) top well kill attempt was the first attempt to utilize an
18 engineered approach—some documents indicate that well kill modeling had been
19 attempted prior to the job. It appears that the well was almost dead when the surface

²³⁶ Blade Report at p. 151.

²³⁷ Blade Report at p. 151.

²³⁸ Blade Report at p. 151.

²³⁹ Blade Report at p. 151.

²⁴⁰ Blade Report at p. 151.

²⁴¹ Blade Report at p. 151.

²⁴² Blade Report at p. 151.

²⁴³ Blade Report at p. 152.

²⁴⁴ Blade Report at p. 152.

²⁴⁵ Blade Report at p. 152.

²⁴⁶ Blade Report at p. 152.

1 equipment failed, but because of the inability to continuously fill the well, the production
2 zone resumed flowing after some (undetermined) time.²⁴⁷

3 The 11 ¾ inch x seven-inch annulus valve on the wellhead backed out during this
4 kill attempt, which created an unrestricted gas flow path to the surface.²⁴⁸ The gas flow
5 out of the two-inch threaded outlet contributed to the enlargement of the crater on the
6 south side.²⁴⁹ It is likely that the crater, unsupported lines and valves, wellhead
7 movement, and vibration contributed to the valve backing out, which made the overall
8 surface situation worse.²⁵⁰

9 Blade concluded that the seventh well kill attempt was a “near kill” that failed
10 because the pumping was terminated early due to concern for potential wellhead
11 damage.²⁵¹ A contributing factor was the cumulative damage done by previous,
12 unsuccessful kill attempts to the well site and wellhead, which caused this kill attempt to
13 be terminated early.²⁵²

14 By December 22, 2015, after more than 4,000 bbl of various fluids had been
15 pumped into the well, most fluids returned to the surface under high velocity.²⁵³
16 Additionally, a large volume of gas had escaped through the surface fissures and crater.²⁵⁴
17 The surface conditions had deteriorated to a point that it became unsafe for personnel to
18 work near the wellhead.²⁵⁵ The relief well P-39A started being drilled on
19 December 4, 2015, and it was successful in killing SS-25 on February 11, 2016.²⁵⁶

²⁴⁷ Blade Report at p. 152.

²⁴⁸ Blade Report at p. 152.

²⁴⁹ Blade Report at p. 152.

²⁵⁰ Blade Report at p. 152.

²⁵¹ Blade Report at p. 152.

²⁵² Blade Report at p. 152.

²⁵³ Blade Report at p. 152.

²⁵⁴ Blade Report at p. 152.

²⁵⁵ Blade Report at p. 152.

²⁵⁶ Blade Report at p. 152.

1 There were no data that indicated transient modeling, any modeling, or analysis
2 was conducted to design the second through sixth well kill attempts.²⁵⁷ Some
3 calculations may have been done; however, gas flow rates were not incorporated into any
4 kill design.²⁵⁸ The decisions appeared to be based on the static reservoir pressure and
5 this would be inadequate and inappropriate for designing kills.²⁵⁹ SoCalGas-provided
6 information suggested that the well-control company was using 30 MMscf/D²⁶⁰ as the
7 well flow rate.²⁶¹ It is unclear whether this information was ever used in any modeling.²⁶²
8 Flow rate and kill fluid density have to be designed by using established industry
9 modeling tools before preparing an operational plan to ensure the well is killed.²⁶³ Each
10 kill attempt caused additional damage to the wellhead and well site.²⁶⁴

11 The 20 days after the first unsuccessful kill attempt were spent gathering data
12 about the well condition and preparing the site for the subsequent well kill operations.²⁶⁵
13 An ice plug in the tubing was found to be at 473 feet.²⁶⁶ A coil tubing unit was rigged up
14 and used to clear out the plug.²⁶⁷ Noise, temperature, pressure, and spinner logs were
15 run.²⁶⁸ Pressure data were recorded.²⁶⁹ A bridge plug was set in the tubing at 8,393 ft.

²⁵⁷ Blade Report at pp. 159, 228.

²⁵⁸ Blade Report at p. 159.

²⁵⁹ Blade Report at p. 228.

²⁶⁰ MMscf/D stands for million standard cubic feet per day.

²⁶¹ Blade Report at p. 228.

²⁶² Blade Report at p. 228.

²⁶³ Blade Report at p. 228.

²⁶⁴ Blade Report at p. 159.

²⁶⁵ Blade Report at p. 226.

²⁶⁶ Blade Report at p. 226.

²⁶⁷ Blade Report at p. 226.

²⁶⁸ Blade Report at p. 226.

²⁶⁹ Blade Report at p. 226.

1 and holes were punched in the tubing at 8,387 ft to allow circulation down the tubing and
2 into the annulus.²⁷⁰ Gas continued to flow throughout this time.²⁷¹

3 At the point in time 20 days after the first unsuccessful kill attempt, and by the
4 time of the second well kill attempt, the scope of the well-control problem should have
5 been better understood.²⁷² It was clear that there was a leak in the 7-inch casing at a
6 shallow depth.²⁷³ Gas was flowing from the reservoir up through the 7-inch casing × 2
7 7/8-inch tubing annulus and then outside of the 7-inch casing at the leak depth.²⁷⁴ The
8 gas was escaping into the surrounding formation and some was migrating to the
9 surface.²⁷⁵ The bottomhole pressure of the reservoir and the tubing and casing pressures
10 at surface were known.²⁷⁶ Annual flow test data were available for SS-25, and an inflow
11 performance curve could have been generated.²⁷⁷ These data would have allowed
12 calculation of a reasonable estimate of the gas flow rate.²⁷⁸

13 There is data indicating that the design of the seventh well kill attempt was
14 modeled ahead of time.²⁷⁹ The well-control company appeared to assume a gas flow rate
15 of around 25–30 MMscf/D, whereas Blade-estimated flow rate was 60 MMscf/D.²⁸⁰
16 However, the annulus pressure dropped to 0 psi for a time indicating that the well had
17 likely been killed, but pumping had to be stopped because of severe vibrations of the
18 wellhead.²⁸¹ The wellhead movement caused pumping lines to break off, and operations

²⁷⁰ Blade Report at p. 226.

²⁷¹ Blade Report at p. 226.

²⁷² Blade Report at p. 226.

²⁷³ Blade Report at p. 226.

²⁷⁴ Blade Report at p. 226.

²⁷⁵ Blade Report at p. 226.

²⁷⁶ Blade Report at pp. 226-227.

²⁷⁷ Blade Report at p. 227.

²⁷⁸ Blade Report at p. 227.

²⁷⁹ Blade Report at p. 228.

²⁸⁰ Blade Report at p. 228.

²⁸¹ Blade Report at p. 228.

1 were stopped to prevent damage to the wellhead itself.²⁸² The inability to continuously
2 fill the well allowed the production zone to resume flowing.²⁸³ No further attempts were
3 made to top kill the well.²⁸⁴

4 It appears that the approach to killing the well was based on a static estimation of
5 bottomhole pressure to determine the kill fluid density and concern about pump pressures
6 exceeding the nominal wellhead pressure rating of 5,000 psi.²⁸⁵ A transient kill model
7 would have revealed that a kill fluid density of 12 ppg or higher at flow rates around 10
8 bpm would have successfully controlled the well with pump pressures below the
9 wellhead rating.²⁸⁶ The well could therefore have been top killed earlier. Instead, a
10 variation of the same initial kill attempt was implemented during the second through
11 sixth well kill attempts with low density kill fluids.²⁸⁷ As shown in this section, the lack
12 of modelling resulted in multiple unsuccessful well kill attempts, and extended the time
13 before the release of gas could be controlled. As noted by Blade, this loss of time caused
14 the well site to deteriorate with the continued gas flow.²⁸⁸ External well-control
15 specialists provide necessary experience and expertise; however, underground storage
16 operators should also have personnel with the necessary skills to monitor and manage
17 external specialists, a core skill for the gas storage operator.²⁸⁹

18 Table 2 below shows the descriptions and results for the well kill attempts
19 between October 23 and December 22, 2015.²⁹⁰

20 **Table 2: Descriptions and Results for Kill Attempts #1-7 (October 23-December 22, 2015)**

21

Commented [GD1]: Margaret. Do you have the expertise to say something along the lines of "underground storage operators, including SoCalGas, should have personnel with the skills to do XYZ, even if they rely on third party well-control specialists, such as Halliburton, to do ABC. The multiple kill attempts demonstrate..."

²⁸² Blade Report at p. 228.

²⁸³ Blade Report at p. 228.

²⁸⁴ Blade Report at p. 228.

²⁸⁵ Blade Report at p. 240.

²⁸⁶ Blade Report at p. 240.

²⁸⁷ Blade Report at p. 240.

²⁸⁸ Blade Report at p. 240.

²⁸⁹ Blade Report at p. 240.

²⁹⁰ Blade Report at pp. 144-146, Table 18.

Kill Attempt & Date	Description	Results	Successful
#1 (October 24)	10 ppg polymer pill (down tubing)	Tubing plugged after 11.8 bbl pumped.	No
	8.6 ppg lease water (down casing in pump-and-bleed operation)	Additional gas flow noted at surface Gas broke through at surface after 89 bbl of fluid pumped.	
#2 (November 13)	10 bbl of 9.4 ppg polymer pill 683 bbl of 9.4 ppg CaCb 10 bbl of 9.4 ppg polymer pill 3 bbl of 8.6 ppg brine water Maximum pump rate 8 bpm Maximum pump pressure 1,526 psi	Observed increased gas flow and liquid from fissures. Pony motor went down. Shut down pumping. Brine, oil, and gas flowing from fissures on pad. Well blew out in the conventional sense. Blowout vent opened 20 ft from wellbore, shooting debris 75 ft into the air.	No
#3 (November 15)	170 bbl of 9.4 ppg CaCh 19 bbl of 18 ppg barite pill 50 bbl of 9.4 ppg CaCl2 Maximum pump rate 8 bpm Maximum pump pressure 1,645 psi	Gas rate from fissures increased, followed by oil and brine. Flow from fissures stopped briefly and then began to flow gas.	No
#4 (November 18)	230 bbl of 9.4 ppg CaCl2 35 bbl of 18 ppg barite pill SO bbl of 9.4 ppg CaCl Maximum pump rate 9 bpm Maximum pump pressure 1,975 psi	Gas rate from fissures increased. Observed oil and brine from fissure. Barite to surface was reported.	No
#5 (November 24)	50 bbl of 9.4 ppg GEO Zan pill 950 bbl of fresh water 35 bbl of 18 ppg barite pill 56 bbl of 9.4 ppg CaCh Maximum pump rate 13 bpm Maximum pump pressure 4,167 psi (Reported value. Telemetry system shows maximum tubing pressure of approximately 3,600 psi)	30ft x 10ft crater developed and gas rate increased. Recovered 700 bbl of fluid from location.	No
#6 (November 25)	50 bbl of 9.4 ppg GEO Zan LCM pill 910 bbl of fresh water 100 bbl of 9.4 ppg GEO Zan LCM pill 56 bbl of 9.4 ppg CaCb Maximum pump rate 13 bpm Maximum pump pressure 4,164 psi	Gas activity increased in crater. Water flow from crater increased. Flow line from 7 in. and tubing head broke. Nipple on wellhead broke. Pump line to 7 in. casing head broke. Cratering around the wellhead increased and damaged several casing valves. Tubing pressure went to zero, and then started increasing.	No
#7 (December 22)	107 bbl of 15 ppg WBM 100 bbl of 15 ppg WBM with LCM 125 bbl of 15 ppg WBM	Mud, oil mist in crater. Liquid began to come out of the casing at surface.	No

	Maximum pump rate 5.8 bpm Maximum pump pressure 1,157 psi (at start conditions)	Shut down due to rocking of wellhead and unloading mud from crater. Pump line to top tee broke off due to movement of wellhead. Tubing pressure went to zero, and then started increasing.
--	---	--

1 In Blade’s view, the first well kill attempt was a reasonable response because the
2 extent of the failure in SS-25 was unknown.²⁹¹ Also in Blade’s view, the scope of the
3 well-control problem should have been better understood 20 days after the first well kill
4 attempt because that time was spent gathering the data about well condition and
5 preparing the site for the subsequent well kill operations.²⁹² Given that SoCalGas had no
6 well kill control plan in certain instances and there are no data indicating transient
7 modeling, any modeling, or analysis conducted to design the second through sixth well
8 kill attempts, and such modeling would have provided the necessary information to
9 successfully kill the well, SoCalGas violated Section 451.

10 The Section 451 violation began November 13, 2015, the day SoCalGas
11 unsuccessfully executed the second well kill attempt without modeling, and continued
12 through February 11, 2016, the date of the successful relief well kill attempt. Because the
13 second through sixth well kill attempts should have been successful with proper
14 modeling, shareholders should be required to pay all expenses associated with each one.
15 Also, because the relief well was started on December 4, 2015,²⁹³ after the second well
16 kill attempt, the relief well would not have been needed had the second well kill attempt
17 been properly modeled. As such, shareholders should be required to pay all expenses
18 associated with the relief well. SoCalGas’s failure to provide well kill programs for relief
19 well #2, well SS-25A and well SS-25B each constitute one violation of Section 451, for a
20 total of three violations. Each of these violations span from November 13, 2015, the date
21 SoCalGas unsuccessfully executed the second well kill attempt, to February 11, 2016, the
22 date of the successful relief well kill attempt.

²⁹¹ Blade Report at p. 148.

²⁹² Blade Report at p. 226

²⁹³ Blade Report at p. 13.

1 Because surface plumbing failures prevented the well from being kept filled and
2 the wellhead and surface casing were structurally unstable by kill attempt 6,²⁹⁴ such
3 damage appears to have resulted from the prior unsuccessful kill attempt, thereby
4 compromising the ability of kill attempt 7 to kill the well and end the safety
5 consequences of the SS-25 leak. According to Blade, pumping for kill attempt 7 was
6 terminated due to rocking of the wellhead and a subsequent failure of the injection
7 connection.²⁹⁵ In other words, the ability to succeed on the seventh kill attempt was
8 impaired by at least certain of the prior unsuccessful kill attempts, which should have
9 been successful. This is a violation of Section 451.

10 The apparent conservative start date of this violation is November 25, 2015, the
11 date that well kill attempt #6 was made.²⁹⁶ This violation continued until February 11,
12 2016, the date of the successful relief well kill attempt.

13 **SoCalGas did not employ reasonable understanding of the**
14 **groundwater depths relative to the surface casing shoe and**
15 **production casing of well SS-25, until two groundwater wells**
16 **were drilled for RCA purposes after the October 23, 2015**
17 **incident at SS-25.**

18 **a) Groundwater Caused Corrosion on the Corrosion on the**
19 **7 Inch and 11 ¾ Inch Casings on SS-25**

20 One of the direct causes for the uncontrolled release of hydrocarbons for 111 days
21 from SS-25 was an axial rupture due to external microbial corrosion on the 7 inch casing
22 outside diameter caused by the groundwater.²⁹⁷ Groundwater accessed the 11 ¾ inch x 7
23 inch annulus and provided an environment conducive to microbial corrosion.²⁹⁸

24 The shallow groundwater above 400 feet accessed the poorly cemented 11 ¾-inch
25 surface casing and caused localized corrosion on the outside surface of that casing.²⁹⁹

²⁹⁴ Blade Report at p. 151.

²⁹⁵ Blade Report at p. 151.

²⁹⁶ See Blade Report at pp. 144-146, Table 18.

²⁹⁷ Blade Report at p. 4.

²⁹⁸ Blade Report at p. 4.

²⁹⁹ Blade Report at p. 3.

1 The Blade RCA Report found that both the 7 inch and 11 ¾ inch metal casings were
2 corroding from the outside as a result of contact with groundwater.³⁰⁰ This groundwater
3 and microbes—likely methanogens, a form of Archaea—caused the corrosion.³⁰¹

4 The RCA field investigation stated generally that surface runoff water permeates
5 the ground and followed fractures and faults down to various depths.³⁰² At the SS-9 well
6 location, approximately 600 ft away from SS-25, Blade observed groundwater at depths
7 above 400 ft and below 900 ft.³⁰³ Except for runoff water, there are no other sources of
8 groundwater at Aliso Canyon.³⁰⁴

9 In the SS-25 well, groundwater displaced the original drilling fluid over a period
10 of time and caused the 7-inch production casing to corrode from the outside.³⁰⁵ This
11 groundwater and biological microbes—likely methanogens, a form of Archaea—caused
12 the corrosion.³⁰⁶ Some of the 7-inch casing connections were seeping gas to the outside
13 of the casing.³⁰⁷ The carbon dioxide in the gas was likely a nutrient for the
14 methanogens.³⁰⁸ The SS-25 casing corrosion area discovered 892 feet down the well by
15 the RCA was 9.25 inches in length and contained grooves from tunnels created by the
16 microbes that coalesced over a period of time.³⁰⁹ The corrosion removed 85% of the wall
17 thickness in a smaller patch of 2.13 inches within the larger 9.25-inch corroded region.³¹⁰

18 The 7 inch production casing exhibited external corrosion on the outside diameter
19 at depths higher than 700 feet.³¹¹ For corrosion to occur, an aqueous environment had to

³⁰⁰ Blade Report at p. 3.

³⁰¹ Blade Report at p. 3.

³⁰² Blade Report at p. 3.

³⁰³ Blade Report at p. 3.

³⁰⁴ Blade Report at p. 3.

³⁰⁵ Blade Report at p. 3.

³⁰⁶ Blade Report at p. 3.

³⁰⁷ Blade Report at p. 3.

³⁰⁸ Blade Report at p. 3.

³⁰⁹ Blade Report at p. 3.

³¹⁰ Blade Report at p. 3.

³¹¹ Blade Report at p. 87.

1 be present in the annulus.³¹² When SS-25 was constructed, the cementing operations
2 displaced cement to 7,000 ft, leaving drilling fluid above the top of cement.³¹³ This
3 drilling fluid would have been the environment that existed behind the 7-inch production
4 casing following construction.³¹⁴ An assessment of the drilling records revealed the
5 possible properties of the drilling fluid that were used in 1954.³¹⁵ The fluid was water-
6 based with some minor additions of oil.³¹⁶ One of the main factors for corrosion is the
7 pH of the drilling fluid; the higher the pH, the lower the corrosion rate.³¹⁷ The pH was
8 elevated, ranging from 10 to 12.5, which is normal for drilling fluid.³¹⁸ Such an
9 environment would not corrode the carbon steel.³¹⁹ The outside diameter of the 7 inch
10 production casing would not have exhibited outside diameter corrosion if the
11 environment had remained the same as the drilling fluid.³²⁰

12 The fluid behind the 7-inch production casing had to be different than the original
13 drilling fluid since there was corrosion on the production casing outside diameter
14 surface.³²¹ There had to be an environment that was more dynamic, created by
15 groundwater or another water source.³²² Water injection from water disposal and other
16 conventional oil production operations were considered in the RCA Report; however the
17 injection depths were significantly deeper and water injection wells were located farther
18 away and closer to many other wells.³²³ Consequently, groundwater was the only
19 feasible source of water that could have occupied the space between the 7-inch

³¹² Blade Report at p. 87.

³¹³ Blade Report at p. 87.

³¹⁴ Blade Report at p. 87.

³¹⁵ Blade Report at p. 87.

³¹⁶ Blade Report at p. 87.

³¹⁷ Blade Report at p. 87.

³¹⁸ Blade Report at p. 87.

³¹⁹ Blade Report at p. 87.

³²⁰ Blade Report at pp. 87-88.

³²¹ Blade Report at p. 88.

³²² Blade Report at p. 88.

³²³ Blade Report at p. 88.

1 production and 11¼-inch surfaces casing (7 x 11¼-inch annulus).³²⁴ Similarly,
2 groundwater is the only water source that could have caused the 11¼-inch casing outside
3 diameter wall corrosion.³²⁵

4 In order to confirm the presence of groundwater, Blade requested SoCalGas to
5 drill a borehole to 1,100 ft to locate possible water sources.³²⁶ The intent was to confirm
6 the source of the water that may have impacted SS-25.³²⁷

7 Blade Figure 82 shows the elevation map around Aliso Canyon field, including
8 SS-25.³²⁸ The source of groundwater was found in topographic contours between 2,354-
9 2,496 feet above sea level.³²⁹ However, there are no surface lakes or rivers within these
10 contours.³³⁰ Precipitation that falls within these contours can be the only source of this
11 water.³³¹

12 Since precipitation is the source of groundwater, groundwater level should be
13 related to precipitation level.³³² First, groundwater level will vary within a given rain
14 year.³³³ The groundwater level will rise during the rainy period from December to
15 March, reaching its highest level at the end of the rainy period in March.³³⁴ The
16 groundwater will then fall during the dry period from March to November, reaching its
17 lowest level at the beginning of the subsequent rainy period.³³⁵ In addition, groundwater
18 level will also vary from year to year.³³⁶ Consequently, the water level in the production

³²⁴ Blade Report at p. 88.

³²⁵ Blade Report at p. 88.

³²⁶ Blade Report at p. 88.

³²⁷ Blade Report at p. 91.

³²⁸ Blade Report at p. 96.

³²⁹ Blade Report at p. 96.

³³⁰ Blade Report at p. 96.

³³¹ Blade Report at p. 96.

³³² Blade Report at p. 97.

³³³ Blade Report at p. 97.

³³⁴ Blade Report at p. 97.

³³⁵ Blade Report at p. 97.

³³⁶ Blade Report at p. 97.


1 casing annulus will rise and fall with the seasons and the extent of precipitation.³³⁷
2 Further, the water level in the annulus would have been at its lowest during the period of
3 the incident.³³⁸
4 The groundwater resulting from run-off rainwater likely entered the annulus and
5 replaced the drilling fluid over time; or mixed with the drilling fluid and the composition
6 of the annulus fluid changed over time.³³⁹ These are all possibilities, however, based on
7 the evidence, the groundwater is ubiquitous and played a role in the external corrosion of
8 the 7 inch casing.³⁴⁰

³³⁷ Blade Report at p. 98.

³³⁸ Blade Report at p. 98.

³³⁹ Blade Report at p. 99.

³⁴⁰ Blade Report at p. 99.



1 Figure 85 from RCA Report, shown above, is entitled “Likely Mechanism of
 2 Groundwater Ingress into the Surface Casing and Production Casing Annuli”.³⁴¹

3 Factors that control the chemical nature of the groundwater are mineralogy,
 4 transmissibility, and topography.³⁴² Generally, natural waters contain few dissolved

³⁴¹ Blade Report at p. 100.

³⁴² Blade Report at p. 91.

1 constituents, with cations and anions in chemical equilibrium.³⁴³ The common cations
2 include two alkaline earths (calcium and magnesium) and an alkali (sodium).³⁴⁴ The
3 anions are bicarbonate, sulfate, and chloride.³⁴⁵ There were distinct shallow (340 to 440
4 feet) and deeper (900 to 1,000 feet) groundwater with slight differences in water
5 chemistry.³⁴⁶ This water likely represented the environment in the production casing
6 annulus and outside of the surface casing.³⁴⁷

7 By allowing groundwater to cause corrosion on the 7 inch and 11 ¾ inch casings
8 on SS-25, SoCalGas violated Section 451. This violation begins on August 30, 1988, the
9 date SoCalGas produced its Interoffice memo calling for inspections of the SS-25
10 casing,³⁴⁸ and continues to October 23, 2015, the beginning date of the incident.

11 **b) SoCalGas Did Not Assess the Relationship Between**
12 **Groundwater In and Around the SS-25 Well Site, and The**
13 **Surface Casing Corrosion of That Well.**

14 Blade did not find any SoCalGas records that identified the location and nature of
15 the groundwater in and around the SS-25 well site.³⁴⁹ Consequently, a correlation of the
16 groundwater locations and the depth of surface casing shoes, and an assessment of the
17 potential for surface casing corrosion were not done.³⁵⁰ The possible corrosion risks to
18 surface casings or production casings were unknown.³⁵¹ The corroded surface casing in
19 SS-25 provided an easy pathway for gas to escape to the surface.³⁵² There is substantial
20 literature regarding groundwater, and in order to understand the hydrochemical nature of

³⁴³ Blade Report at p. 91.

³⁴⁴ Blade Report at p. 91.

³⁴⁵ Blade Report at p. 91.

³⁴⁶ Blade Report at p. 93.

³⁴⁷ Blade Report at p. 93.

³⁴⁸ Blade Report at p. 218; Southern California Gas Company, "Candidate Wells for Casing Inspection, Aliso Canyon Field, Interoffice Correspondence, August 30, 1988 AC_CPUC_0000064-AC_CPUC_0000066 (SS-25 Well Documentation (from SoCalGas_N.pdf at pp. 42-44)," 1988.

³⁴⁹ Blade Report at p. 239.

³⁵⁰ Blade Report at p. 239.

³⁵¹ Blade Report at p. 239.

³⁵² Blade Report at p. 239.

1 the water, it is necessary to understand the relation between the chemical character of the
2 water, mineralogy of the environment, and circulation of the water.³⁵³

3 SoCalGas's failure to assess the relationship between groundwater in and around
4 the SS-25 wellsite, and the surface casing corrosion of that well on SS-25 constitute a
5 violation of Section 451. This violation begins on August 30, 1988, the date SoCalGas
6 produced its Interoffice Memo calling for inspections of the SS-25 casing,³⁵⁴ and
7 continues to October 23, 2015, the beginning date of the incident.

8 **SoCalGas did not have systematic practices to protect surface**
9 **casing strings against external corrosion.³⁵⁵ Therefore,**
10 **SoCalGas did not employ proper understanding of the**
11 **consequences of corroded surface casings and uncemented**
12 **production casings.³⁵⁶**

13 During the RCA Investigation Phase 3 evaluation of the condition of the 11 ¾-
14 inch surface casing, holes in the casing were found between 134 feet and 300 feet.³⁵⁷
15 These holes were caused by the escaping gas pressure following external corrosion
16 because the casing was neither fully cemented nor cathodically protected leaving the
17 casing exposed to an environment conducive to corrosion.³⁵⁸ Cathodic protection
18 systems are commonly used to protect pipelines from corrosion and are sometimes used
19 on well surface casing strings.³⁵⁹ A cathodic protection system would have provided
20 corrosion protection to the 11 ¾-inch casing,³⁶⁰ but would not have protected the 7 inch
21 casing inside the 11 ¾ inch casing.³⁶¹

³⁵³ Blade Report at p. 91.

³⁵⁴ Blade Report, p. 218; Southern California Gas Company, "Candidate Wells for Casing Inspection, Aliso Canyon Field, Interoffice Correspondence, August 30, 1988 AC_CPUC_0000064-AC_CPUC_0000066 (SS-25 Well Documentation (from SoCalGas_N.pdf at pp. 42-44)." 1988.

³⁵⁵ Blade Report at p. 5

³⁵⁶ Blade Report, p. 5.

³⁵⁷ Blade Report at p. 226.

³⁵⁸ Blade Report at p. 226.

³⁵⁹ Blade Report at p. 215.

³⁶⁰ Blade Report at p. 215.

³⁶¹ Blade Report at p. 215.

1 The presence of bonded cement outside of the 7 inch casing would have mitigated
2 external corrosion.³⁶² However, there was no cement around the 7 inch casing at 892
3 feet, because when the well was originally drilled, the cement around the 7 inch casing
4 was intentionally brought up to 7,000 feet and not to surface.³⁶³

5 Surface casing cathodic protection had been applied to five other wells at Aliso
6 Canyon, but not to SS-25.³⁶⁴ The most common method for providing corrosion
7 protection for casing strings is to manage the environment or to modify the casing
8 metallurgy.³⁶⁵

9 A SoCalGas Interoffice correspondence dated August 20, 1991,³⁶⁶ discussed an 8-
10 5/8-inch casing inspection log showing metal loss and a corrosion protection log run in
11 FF-34A.³⁶⁷ A recommendation was made to equip FF-34A with cathodic protection
12 (CP).³⁶⁸ CP was implemented in FF-34A and four other wells according to SoCalGas in
13 response to a February 18, 2018, information request.³⁶⁹ The document also states that:

14 ...The possible regional external casing corrosion problem in
15 the southeastern portion of the field will be further studied
16 and a report issued. Additional investigation of well histories
17 and well logs is required before a recommendation can be
18 made as to whether regional CP is necessary. While casing
19 inspection logs show shallow (1000 feet to 3000 feet ELM),
20 casing metal loss in FF-35C, MA-1A and MA-5A, there is
21 not enough evidence to substantiate a regional corrosion
22 problem....³⁷⁰

³⁶² Blade Report at p. 215.

³⁶³ Blade Report at p. 215.

³⁶⁴ Blade Report at p. 226.

³⁶⁵ Blade Report at p. 215.

³⁶⁶ Blade Report at p. 173.

³⁶⁷ Blade Report at p. 173.

³⁶⁸ Blade Report at p. 173.

³⁶⁹ Blade Report at p. 173.

³⁷⁰ Blade Report at p. 173, citing Attachment 7001-AC_CPUC_0022179; Southern California Gas Company Interoffice Correspondence, "FF-34A Casing Corrosion, Aliso Canyon", August 20, 1991, AC_BLD_0033271 (FF-34A Well Documentation from SoCal.pdf at p. 183)," 1991.

1 In the data provided, Blade was not able to find documentation with results of the
2 proposed study or if the study was done or not.³⁷¹ Also, the FF-34A well file mentioned
3 that the possible external casing corrosion problem in the southeastern portion of the field
4 was to be further studied and a report issued,³⁷² but Blade was not able to locate any
5 documentation related to this study.³⁷³

6 SoCalGas violated Section 451 because it did not have systematic practice to
7 protect surface casing strings against external corrosion,³⁷⁴ and because it did not
8 understand the consequences of corroded surface casings and uncemented production
9 casings.³⁷⁵ This violation begins on August 30, 1988, the date SoCalGas produced its
10 Interoffice Memo calling for inspections of the SS-25 casing,³⁷⁶ and continues to October
11 23, 2015, the beginning date of the incident.

12 **SoCalGas lacked a real-time, continuous pressure monitoring**
13 **system for well surveillance, which prevented an immediate**
14 **identification of the SS-25 leak and accurate estimation of the**
15 **gas flow rate.³⁷⁷**

16 On October 23, 2015, the SS-25 well went back on injection between 3 AM and 4
17 AM.³⁷⁸ The SS-25 axial rupture likely occurred after injection had started.³⁷⁹ At the time
18 of failure, SS-25 was injecting gas into the reservoir.³⁸⁰ The subsequent circumferential
19 parting occurred between 7 AM and 8 AM the same day.³⁸¹

³⁷¹ Blade Report at pp. 173, 203.

³⁷² Blade Report at p. 2.

³⁷³ Blade Report at p. 2.

³⁷⁴ Blade Report at p. 5.

³⁷⁵ Blade Report at p. 5.

³⁷⁶ Blade Report at p. 218; Southern California Gas Company, "Candidate Wells for Casing Inspection, Aliso Canyon Field, Interoffice Correspondence, August 30, 1988 AC_CPUC_0000064_AC_CPUC_0000066 (SS-25 Well Documentation (from SoCalGas) N.pdf at pp. 42-44)." 1988.

³⁷⁷ Blade Report at p. 5.

³⁷⁸ Blade Report at p. 158.

³⁷⁹ Blade Report at p. 158.

³⁸⁰ Blade Report at p. 158.

³⁸¹ Blade Report at p. 158.

1 Upon failure, the initial leak rate was 160 million standard cubic feet per day
2 (MMscf/D).³⁸² 90 MMscf/D from this rate originated from the gas storage reservoir, and
3 the remaining 70 MMscf/D originated from the injection network.³⁸³

4 The injection network was capable of supplying this additional gas rate to
5 SS-25.³⁸⁴ The pressure changes, as the injection network readjusted to supply this
6 additional gas rate to SS-25, were too small to be detected in real time with the
7 surveillance system in operation at the time.³⁸⁵ To detect the failure in real time, a
8 surveillance system would have had to be monitoring wellhead injection pressures
9 between the chokes and wellheads.³⁸⁶

10 The lack of real-time pressure measurements prevented the immediate
11 identification of the SS-25 7-inch casing failure.³⁸⁷ The constant monitoring of the
12 tubing, production casing and surface casing pressures will provide better insight into
13 operational deviations in all wells.³⁸⁸ If this type of system had been installed on SS-25,
14 it would have provided insight into the time of the leak, the opportunity to shut in the
15 well immediately, size of the leak, and the extent of the problem.³⁸⁹ Furthermore, the
16 information could have used during well-control effort improving the chances of an early
17 success.³⁹⁰

18 The existing field and SS-25 well measurements were used by Blade after the
19 event to analyze the leak.³⁹¹ Such measurements could have been analyzed before and
20 during the leak event with models built from data available before the leak.³⁹²

³⁸² Blade Report at p. 158.

³⁸³ Blade Report at p. 158.

³⁸⁴ Blade Report at p. 158.

³⁸⁵ Blade Report at p. 158.

³⁸⁶ Blade Report at p. 158.

³⁸⁷ Blade Report at p. 233.

³⁸⁸ Blade Report at p. 233.

³⁸⁹ Blade Report at p. 233.

³⁹⁰ Blade Report at p. 233.

³⁹¹ Blade Report at p. 127.

³⁹² Blade Report at p. 127.

1 Although SoCalGas performed 41 pressure surveys in 41 years, neither the
2 *DOGGR Project Approval Letter* nor the *SoCalGas Gas Inventory-Monitoring,*
3 *Verification, and Reporting Company Operations Standard Gas Operations* required
4 pressure surveys.³⁹³ The most recent SS-25 pressure survey occurred on October 21,
5 2014, to 8,720 feet.³⁹⁴ Blade’s interpretation of the pressure surveys is that they were not
6 effective in determining the presence or location of a casing leak; small leaks would go
7 undetected.³⁹⁵ From a casing integrity perspective, pressure surveys differ from pressure
8 tests substantially.³⁹⁶ In pressure surveys, the well is open to the storage zone, and any
9 gas that escapes into a casing leak is replenished by the storage zone.³⁹⁷ This is
10 considerably different than a pressure test where all external sources of pressure are
11 isolated.³⁹⁸ Additionally, the pressures observed during these pressure surveys are the
12 shut-in pressures.³⁹⁹ The pressure profiles during shut-in are lower than during standard
13 gas injection operations.⁴⁰⁰ In other words, pressure surveys are taken at times when the
14 casing is under less pressure than during gas injection.⁴⁰¹

15 SoCalGas operated Aliso Canyon facility according to a number of Company
16 Operations Standards.⁴⁰² These standards provided policy and scope, definitions,
17 responsibility, and procedures that are required to operate the facility on a day to day
18 basis.⁴⁰³ An example standard is titled *Gas Inventory – Monitoring, Verification and*
19 *Reporting.*⁴⁰⁴ Blade’s interpretation is that SoCalGas complied with the monitoring

³⁹³ Blade Report at p. 199.

³⁹⁴ Blade Report at pp. 199-200.

³⁹⁵ Blade Report at p. 199.

³⁹⁶ Blade Report at p. 199.

³⁹⁷ Blade Report at p. 199.

³⁹⁸ Blade Report at p. 199.

³⁹⁹ Blade Report at p. 199.

⁴⁰⁰ Blade Report at p. 199.

⁴⁰¹ Blade Report at p. 199.

⁴⁰² Blade Report at p. 202.

⁴⁰³ Blade Report at p. 202.

⁴⁰⁴ Blade Report at p. 202.

1 components of the Operations Standard titled Gas Inventory – Monitoring, Verification
2 and Reporting.⁴⁰⁵ Blade also reviewed SS-25 noise, temperature, and pressure surveys
3 before the incident of October 23, 2015.⁴⁰⁶ There were no temperature, pressure, or noise
4 anomalies in the surveys that indicated a preexisting casing failure.⁴⁰⁷ Additionally, there
5 were no physical observations from well inspections and weekly pressure measurements
6 that indicated an existing problem.⁴⁰⁸

7 Figure 169 of the Blade Report, shows the Summary of the Aliso Canyon
8 Monitoring Plan for Storage Zone Wells from the SoCalGas Annual Review Meeting
9 with DOGGR, 1989.⁴⁰⁹ The components and frequency of the monitoring plan are listed
10 in Figure 169, but none of them require a real time collection of data.⁴¹⁰ Industry
11 technology has evolved for real time pressure, temperature, flow, and vibration (noise)
12 monitoring but, surprisingly, there were *no* significant differences in the monitoring plan
13 from 1989 compared to the 2014 SCG 224.070 Operations Standard.⁴¹¹ These
14 documents fail to mention casing inspection logs, pressure testing wells, real time
15 pressure monitoring, investigation of leaks, and RCA.⁴¹²

16 SoCalGas violated Section 451 by not having a continuous pressure monitoring
17 system for well surveillance because it prevented an immediate identification of the SS-
18 25 leak and accurate estimation of the gas flow rate. This violation lasted from October
19 23, 2015 to February 12, 2016, the duration of the incident.

⁴⁰⁵ Blade Report at p. 202.

⁴⁰⁶ Blade Report at p. 202.

⁴⁰⁷ Blade Report at p. 202.

⁴⁰⁸ Blade Report at p. 202.

⁴⁰⁹ Blade Report at p. A-3.

⁴¹⁰ Blade Report at p. A-4. See Column entitled “Minimum Frequency of Data Collection”. None of the entries under this column require collection of data real time. Instead, each shows a less frequent requirement for data collection.

⁴¹¹ Blade Report at p. A-3. Emphasis in original.

⁴¹² Blade Report at p. A-4.

1 **C. Additional Violations**

2 **SoCalGas Knew that SS-25 Released Both Crude Oil and**
3 **Natural Gas During the Aliso Canyon Natural Gas Storage**
4 **Incident, But Did Not Disclose This Fact to the Los Angeles**
5 **County Department of Public Health**

6 According to a letter from the Los Angeles County Department of Public Health
7 Deputy Director for Health Protection to SoCalGas’s Chief Executive Officer, SoCalGas
8 did not disclose to the Department of Public Health that the natural gas released from
9 October 23, 2015 to February 12, 2016 contained crude oil, thereby impairing the
10 Department of Public Health’s ability to timely study the associated health impacts.

11 This letter, dated March 11, 2019, noted that SoCalGas repeatedly stated during
12 the disaster that the contents of the release were limited only to typical components of
13 stored natural gas, despite the massive quantity of natural gas released from
14 October 23, 2015 through February 2016 containing crude oil. The letter also pointed out
15 that in November 2015, Public Health recommended a complete characterization of air
16 quality using an expanded list of chemicals found in both crude oil and natural gas, but
17 the testing was severely limited and delayed. At that time, the letter provides, SoCalGas
18 knew that crude oil was contained in the natural gas but withheld this information from
19 Public Health⁴¹³

20 SoCalGas responded to the Department of Public Health ⁴¹⁴ asserting “For all the
21 above reasons, your suggestion that SoCalGas somehow withheld information or was
22 otherwise not fully transparent with respect to the components of natural gas released

⁴¹³ See Attachment U, Letter from Mr. Angelo J. Bellomo, MS, REHS, QEP, Deputy Director for Health Protection of Los Angeles County Department of Public Health to Mr. Brett Lane, Chief Executive Officer, Southern California Gas Company, entitled, “ALISO CANYON NATURAL GAS DISASTER FOLLOW-UP REQUEST FOR CRITICAL DATA ELEMENTS”, March 11, 2019. Currently available at: https://www.cpuc.ca.gov/uploadedFiles/CPUCWebsite/Content/News_Room/NewsUpdates/2019/Aliso%20Canyon%20Facility.pdf.

⁴¹⁴ See Attachment V, Available at: https://www.cpuc.ca.gov/uploadedFiles/CPUCWebsite/Content/News_Room/NewsUpdates/2019/Letter-to-Angelo-J-Bellomo-2019-03-21-1.pdf.

1 during the incident, and your statements concerning DPH's ability to perform a health
2 assessment, are simply incorrect."⁴¹⁵

3 The statements in the Los Angeles County Department of Public Health Letter and
4 statements related to that letter identify SoCalGas's failure to furnish reasonable service,
5 instrumentalities, equipment and facilities as are necessary to promote the health of its
6 patrons, employees, and the public, and constitute at least one violation of Section 451.
7 At a minimum, this violation begins at least as early as November 2015, when "SoCalGas
8 knew that crude oil was contained in the natural gas but withheld this information from
9 Public Health,"⁴¹⁶ and continues until at least February 12, 2016, because SoCalGas
10 "repeatedly stated during the disaster that the contents of the release were limited only to
11 typical components of stored natural gas" through that date. These dates and the precise
12 nature of this violation may be modified pending additional testimony from intervening
13 parties to this proceeding with expertise in public health.

14 **██████████ In Multiple Instances, SoCalGas Did Not Cooperate with SED**
15 **During Its Pre-Formal Investigation Following the Incident on**
16 **Aliso Well SS-25 that Began on October 23, 2015**

17 The Assigned Commissioner's Scoping Memo and Ruling (Scoping Memo) asks,
18 "Did SoCalGas cooperate sufficiently with SED and Blade during the pre-formal
19 investigation that preceded the issuance of the OII/OSC?"⁴¹⁷ As shown by the list of
20 examples below, SoCalGas has not cooperated with SED's investigation. Each example
21 constitutes a violation of Section 451 because it impaired SED's ability to investigate
22 SoCalGas's practices related to the safe operation of the Aliso Canyon Storage Facility,
23 as it relates to the incident at SS-25. Where identified in the examples, the lack of
24 cooperation also constitutes a violation of Commission Rule of Practice and Procedure
25 Rule 1.1.

⁴¹⁵ See Attachment V, Available at:
https://www.cpuc.ca.gov/uploadedFiles/CPUCWebsite/Content/News_Room/NewsUpdates/2019/Letter-to-Angelo-J-Bellomo-2019-03-21-1.pdf.

⁴¹⁶ Attachment U at p. 2.

⁴¹⁷ I.19-06-016, Assigned Commissioner's Scoping Memo and Ruling at p. 4, Question 3.

1 **D. Example 1: SoCalGas Did Not Completely Answer the Discovery of the**
2 **Aliso Root Cause Analysis Consultants, Blade Energy Partners, and**
3 **Then Provided a Data Dump As a Supplement These Incomplete**
4 **Responses Up to Three Years Later, and Weeks Before Blade's**
5 **Announced Release Date of Its Root Cause Analysis**

6 On March 15, 2019, Blade Energy Partners (Blade) was required to move its
7 estimated RCA date from March 31, 2019 to May 1, 2019.⁴¹⁸ As stated by Blade in
8 explanation of the move.⁴¹⁹

9 Just prior to the week of February 27, 2019 SoCal Gas, for the first time, informed
10 Blade that it was supplementing its data responses to certain Blade data requests that
11 Blade issued as part of its RCA, all of which were previously thought to be complete.
12 The original dates of these Blade data requests were Jan 31, 2016, Feb 19, 2016, April 7,
13 2016, and Feb 18, 2018.

14 On March 1, 2019 and March 6, 2019 Blade received over 25,000 Bates numbered
15 pages along with electronic files for these 2016-2018 data requests.

16 Blade is currently reviewing this massive set of data to determine if it significantly
17 impacts the RCA.

18 The Safety and Enforcement Division is investigating SoCal Gas's timing and
19 practices related to this significant data dump on Blade.

20 In reaction to Blade's statement, on March 19, 2019, the Commission's Executive
21 Director provided a letter to SoCalGas's Chief Executive Officer which stated in part.

22 I am writing regarding the Southern California Gas Company's (SoCalGas) March
23 1 and 6, 2019 supplemental data dump on Blade Energy Partners (Blade). . .

24 On March 1 and 6 of this year, SoCalGas surprised Blade with over 25,000 pages
25 of data, plus additional electronic files in Excel and other formats. This data dump is
26 allegedly a supplemental data response to questions submitted by Blade to SoCalGas in

⁴¹⁸ See https://www.cpuc.ca.gov/uploadedFiles/CPUCWebsite/Content/News_Room/NewsUpdates/2019/RCA%20timeline%20CPUC%20website.pdf; "Blade Energy Partner's Root Cause Analysis (RCA) – Updated Schedule (3/15/19).

⁴¹⁹ See https://www.cpuc.ca.gov/uploadedFiles/CPUCWebsite/Content/News_Room/NewsUpdates/2019/RCA%20timeline%20CPUC%20website.pdf; "Blade Energy Partner's Root Cause Analysis (RCA) – Updated Schedule (3/15/19).

1 2016 and 2018. As SoCalGas was aware, Blade intended to release its RCA of the failure
2 of SS-25 by the end of this month. I am particularly shocked and concerned that
3 SoCalGas would dump these additional 25,000 pages plus of documents and cause delay
4 in the analysis of the well failure. Due to the size and extreme tardiness of SoCalGas's
5 data dump, Blade's RCA will now be delayed as Blade attempts to review, digest, and
6 analyze this new information for purposes of producing its report. . .

7 SoCalGas's lack of cooperation impaired Blade's ability to deliver a complete
8 RCA in a timely fashion.⁴²⁰ Each of the four data dumps constitutes its own separate
9 violation of Section 451. Out of an abundance of caution, the beginning date for each
10 violation should not start until two calendar months after Blade issued each data request.
11 The end date of each violation is March 1, 2019, the first of SoCalGas's supplemental
12 data dumps. In short, the violation dates are:

- 13 • Violation 1: March 31, 2016 to March 1, 2019.
- 14 • Violation 2: April 18, 2016 to March 1, 2019.
- 15 • Violation 3: June 7, 2016 to March 1, 2019.
- 16 • Violation 4: April 7, 2016 to March 1, 2019.

17 **E. Example 2: Despite SED's Subpoenas to Do So, SoCalGas Did Not**
18 **Produce Boots and Coots's Team Lead Well Kill Specialist, and**
19 **Another Boots & Coots Safety Representative, Both of Whom Were**
20 **Onsite for Certain of the Boots & Coots Efforts to Kill Well SS-25, for**
21 **SED to Examine Under Oath**

22 On July 11, 2018, SED issued a letter to SoCalGas entitled, "Memorialization of
23 Southern California Gas Company's (SoCalGas) Failure to Cooperate with Safety and
24 Enforcement Division (SED) in SED's Preliminary Investigation". In this letter, SED's
25 director stated,

26 I have been informed that SoCalGas is not producing certain
27 of its own contractors for SED to examine under oath, even
28 though SED has requested that SoCalGas produce them to
29 appear at the California Public Utilities Commission

⁴²⁰ See Attachment A, Letter from Ms. Alice Stebbins, California Public Utilities Commission's Executive Director, to Mr. Bret Lane, SoCalGas Chief Executive Officer, entitled, "Failure of Southern California Gas Company (SoCalGas) to Timely Provide Data to Blade Energy Partners and Request to Modify the Existing Injection and Withdrawal Protocols at Aliso", March 19, 2019.

1 (Commission) headquarters in San Francisco, CA.
2 Specifically, SED has requested SoCalGas produced its
3 contractors from Halliburton's subsidiary, Boots and Coots,
4 that were hired as part of SoCalGas's efforts to kill well SS-
5 25. In response to SED's request, SED's counsel learned
6 from SoCalGas's counsel on or about the week of June 18,
7 2018 that SoCalGas would produce only one of these
8 contractors to talk with SED investigators and attorneys,
9 either by phone, or in Houston.⁴²¹

10 By not producing all of these requested individuals in person at the Commission
11 headquarters, SoCalGas is not cooperating with SED's direction in this preliminary
12 investigation. . .⁴²²

13 SED's letter continued,

14 SED puts SoCalGas on notice that it is formally requesting SoCalGas produce at
15 the Commission headquarters in San Francisco the following individuals from
16 Boots and Coots:

17 Danny Clayton

18 Danny Walzel

19 James Kopecky

20 Mike Baggett⁴²³

21 On July 13, 2018, SED served four subpoenas on SoCalGas, each requiring that
22 SoCalGas produce an individual who worked for Boots & Coots.⁴²⁴ Thus, in total, the
23 subpoenas required SoCalGas to produce four individuals on August 8th and 9th, 2018.⁴²⁵
24 With the exception of the name, which was specific to each subpoena, in each of these
25 subpoenas, SED attested as follows:

26 [Name of subpoenaed individual-Mr. Clayton, Baggett,
27 Walzel or Kopecky] of Boot & Coots Services, a division of

⁴²¹ See Attachment B, Letter from Ms. Elizaveta Malashenko, Director, Safety and Enforcement Division, CPUC, to Mr. Bret Lane, President and Chief Operating Officers, Southern California Gas Company, dated July 11, 2018.

⁴²² Attachment B at p. 1.

⁴²³ Attachment B at p. 3.

⁴²⁴ See Attachments C, D, E, and F. These documents are subpoenas for the appearance of Danny Clayton, Mike Baggett, Danny Walzel, and James Kopecky, respectively. The date of service is shown on the proof of service in each subpoena.

⁴²⁵ See Attachments C, D, E, and F. These documents are subpoenas for the appearance of Danny Clayton, Mike Baggett, Danny Walzel, and James Kopecky, respectively.

1 Halliburton, may have important information that would help
2 the CPUC as it investigates the cause of the Aliso Canyon gas
3 leak. The CPUC understands that Mr. [Clayton, Baggett,
4 Walzel, or Kopecky] is/was an agent of the Southern
5 California Gas Company and was present at the Aliso Canyon
6 facility in or around November 2015 and the ensuing days,
7 and was actively involved in attempting to “kill” the leaking
8 well.⁴²⁶

9 Also on July 13, SoCalGas responded to SED with a letter entitled, “Southern
10 California Gas Company’s Response to California Public Utilities Commission Letter
11 dated July 11, 2018”. The letter stated in part,

12 I am writing on behalf of Southern California Gas Company
13 (“SoCalGas”) in response to Ms. Malashenko’s letter dated
14 July 11, 2018 regarding SoCalGas’ purported failure to
15 cooperate with the Safety and Enforcement Division’s
16 (“SED”) Preliminary Investigation.

17 First and foremost, SoCalGas has at all times cooperated—
18 and will continue to cooperate—with SED’s investigation of
19 the SS-25 gas leak. However, as SoCalGas has previously
20 stated, it is legally unable to produce current and former
21 employees of an independent, out-of-state, third-party
22 corporation for examination before SED at the California
23 Public Utilities Commission (“Commission”) in San
24 Francisco.⁴²⁷

25 SoCalGas has cooperated to the best of its ability with SED’s
26 request for an interview with Boots & Coots through
27 discussions with Halliburton, Boots & Coots’ parent
28 corporation. SoCalGas has in fact obtained Halliburton’s
29 agreement to produce Boots & Coots personnel for such an
30 interview. SoCalGas has also provided SED with contact
31 information for Halliburton’s outside counsel and worked
32 diligently to produce non-privileged information in its
33 custody, control or possession related to Boots & Coots’ work
34 regarding the gas leak. In fact, Halliburton has agreed that its

⁴²⁶ See Attachments C, D, E, and F, Declaration in Support of the Subpoena, point 5.

⁴²⁷ SoCalGas footnote 1 of Attachment G stated, “Other than Halliburton’s limited provision of services to SoCalGas as an independent contractor, SoCalGas and Halliburton are currently unaffiliated. SoCalGas does not own and holds no interest in Halliburton or any of its subsidiaries, and vice-versa.”

1 current employees can be interviewed via phone, video
2 conference or in person in Houston by the Commission. . .

3 Unlike its own currently employed employees, which
4 SoCalGas can and must produce for SED examinations under
5 oath (and has, in fact, done multiple times in connection with
6 the SS-25 gas leak, including producing on short notice its
7 President and Chief Operating Officer), SoCalGas cannot
8 order Boots & Coots' personnel to follow SoCalGas
9 directives. Again, SoCalGas has asked for Boots & Coots'
10 cooperation and Boots & Coots has offered it, albeit not in
11 precisely the manner that SED prefers. There is nothing else
12 SoCalGas can do to compel Boots & Coots' employees or
13 former employees to fly to California to appear for an
14 interview. . .

15 Next, SED contends that because SoCalGas has asserted a
16 (limited) agency relationship with Boots & Coots, during a
17 limited period of time, for the purposes of preserving
18 privilege over certain communications, SoCalGas must ipso
19 facto be required to produce Boots & Coots under section 702
20 [of the California Public Utilities Code]. The fact that Boots
21 & Coots may be deemed SoCalGas' agent, during a limited
22 period of time, for the limited purpose of assessing attorney-
23 client privilege does not, however, make Boots & Coots
24 SoCalGas' agent in other contexts. That does not change the
25 fact that the two Boots & Coots employees requested by SED
26 were, at all times during the incident, employees of Boots &
27 Coots which was acting as an independent contractor to
28 SoCalGas under a separate contractual agreement.

29 Contrary to your claim that SoCalGas is trying to "evade[]"
30 SED's investigation and discovery rights" by delegating work
31 to contractors, SoCalGas has in fact cooperated fully with
32 SED's request and arranged for SED to interview Boots &
33 Coots, albeit not on SED's preferred terms. In addition, there
34 is nothing that prevents SED from exercising its own
35 authority to subpoena Boots & Coots directly.

36 Because SoCalGas has in fact cooperated with SED's request
37 and obtained Halliburton's agreement to submit to an SED

1 interview, and for the other reasons stated above, SoCalGas
2 respectfully requests that SED withdraw its letter.⁴²⁸

3 SoCalGas's contract with Boots & Coots to do the well kill did not include a
4 provision that required Boots & Coots to subject itself to the same provisions to
5 cooperate with SED's pre-formal investigation that SoCalGas itself was required to
6 follow.⁴²⁹

7 On August, 8, 2018, SoCalGas produced only two of the four subpoenaed Boots
8 and Coots Services employees to be examined under oath by SED.⁴³⁰ The two
9 individuals who appeared testified that a third subpoenaed individual who did not appear,
10 Ms. Danny Clayton, was a senior well control specialist who joined Messrs. Walzel and
11 Kopecky on a visit to the site.⁴³¹ Mr. Clayton was also the team leader of Messrs. Walzel
12 and Kopecky.⁴³² They also testified that the fourth individual, Mr. Mike Baggett, was the
13 safety representative for Boots & Coots.⁴³³

14 As team lead, Mr. Clayton's role was to communicate with the client directly, and
15 coordinated a plan with the client and then Messrs. Walzel and Kopecky would execute
16 the plan.⁴³⁴ As such, Mr. Clayton was the person to receive information from SoCalGas
17 once Messrs. Walzel, Kopecky and Clayton arrived in Los Angeles to begin work on the
18 Aliso Canyon well SS-25.⁴³⁵ Mr. Clayton was the main liaison with Mr. Bret Lane of
19 SoCalGas, and "he was in the trailer with him most of the day", and took over receiving
20 information throughout the Aliso incident while both Messrs. Kopecky and Walzel were

⁴²⁸ See Attachment G, Letter from SoCalGas Assistant General Counsel, Sabina Clorfeine, to SED counsels, Messrs. Nicholas Sher and Darryl Gruen, entitled, "Southern California Gas Company's Response to California Public Utilities Commission Letter dated July 11, 2018.

⁴²⁹ Attachment H, Southern California Gas Company Standard Services Agreement (Agreement 5660044243), Project Standard Senson (Sic) 25, October 30, 2015. (SoCalGas and Boots and Coots Well Kill Agreement).

⁴³⁰ See Attachment I, Examination Under Oath Transcript (Tr.) of Danny Walzel and James Kopecky at pp. 1, 5:10-17.

⁴³¹ Attachment I, EUO Tr. Walzel and Kopecky at pp. 26:3 – 29:19.

⁴³² Attachment I, EUO Tr. Walzel and Kopecky at p. 41:2-4.

⁴³³ Attachment I, EUO Tr. Walzel and Kopecky at p. 119:24-28.

⁴³⁴ Attachment I, EUO Tr. Walzel and Kopecky at p. 80:10-16.

⁴³⁵ Attachment I, EUO Tr. Walzel and Kopecky at pp. 134:1-7, 134:13-22.

1 on site.⁴³⁶ Messrs. Walzel and Kopecky reported directly to Mr. Clayton, and Mr.
2 Clayton was making the decision for Boots & Coots about how to move forward with
3 input from the rest of the Boots & Coots team.⁴³⁷

4 Mr. Baggett stayed on site with Messrs. Kopecky and Walzel for approximately
5 one month.⁴³⁸ Mr. Baggett's main role was to look out after the Boots and Coots team,
6 explain to SoCalGas if Boots & Coots is doing something in a way that might not be
7 normal, and check people in and out of location and keep track of the personnel on
8 location.⁴³⁹

9 Boots and Coots was under contract with SoCalGas to kill well SS-25.⁴⁴⁰ SED's
10 review of that contract shows that SoCalGas did not provide a term in that contract that
11 would require Boots and Coots to respond to investigation related inquiries from SED or
12 from Blade.

13 SoCalGas's failure to produce Mr. Clayton and Mr. Baggett in response to an SED
14 subpoena to do so constitutes two separate violations of Section 451. The beginning date
15 for these violations is August 8, 2018, when neither of them appeared to be Examined
16 Under Oath by SED. As SoCalGas has not produced either of these two individuals, the
17 violation could reasonably continue, but SED will put an end date on the due date of this
18 testimony, November 22, 2019.

⁴³⁶ Attachment I, EUO Tr. Walzel and Clayton at p. 130:8-12.

⁴³⁷ Attachment I, EUO Tr. Walzel and Kopecky at pp. 80:18, 81:12.

⁴³⁸ Attachment I, EUO Tr. Walzel and Kopecky at p. 120:20-26.

⁴³⁹ Attachment I, EUO Tr. Walzel and Kopecky at p. 121:3-15.

⁴⁴⁰ See Attachment H- Southern California Gas Company Standard Services Agreement (Agreement 5660044243), Project Standard Senson (Sic) 25, October 30, 2015. (SoCalGas and Boots and Coots Well Kill Agreement)

1 **F. Example 3: Despite SoCalGas Not Producing Boots & Coots's Team**
2 **Lead Well Kill Specialist, It Refused to Provide Certain**
3 **Communications Between SoCalGas and Boots & Coots, Including**
4 **Some Between that Individual and SoCalGas's President and CEO,**
5 **Claiming Them to Be Privileged As Attorney-Client Communications.**
6 **SoCalGas Later Revealed Some of the Communications It Initially**
7 **Claimed to Be Privileged by Attorney-Client Communications**

8 On February 12, 2018, SED Data Request 16 Question 10 specifically asked of
9 SoCalGas, "Please provide any and all communications relating to Aliso Canyon between
10 SoCalGas and Boots and Coots for the time period October 1, 2015 – January 31,
11 2018."⁴⁴¹

12 On March 5, 2018, SoCalGas responded,

13 "“SoCalGas objects to this request to the extent the response involves attorney-
14 client privileged information and/or attorney work product.” A list of the documents in
15 response to this data request were not disclosed.⁴⁴²

16 Partly in response to data request 16, SED's July 11, 2018 letter to SoCalGas
17 observed:

18 SoCalGas has suggested an agency relationship with Boots & Coots via he
19 attached privilege log (Attachment A), where it specifically asserted attorney-client
20 privilege over multiple communications between SoCalGas and Boots and Coots
21 personnel. Then, SoCalGas refused to produce some of those same Boots and Coots
22 personnel for examination under oath on the basis that they were neither employees nor
23 agents of SoCalGas.⁴⁴³

⁴⁴¹ See Attachment J-SoCalGas' Supplemental Response Dated March 15, 2019 to Multiple SED Data Requests, Including Portions of Data Request 16 at p. 1. SED initially propounded Data Request 16 February 12, 2018.

⁴⁴² See Attachment J-SoCalGas' Supplemental Response Dated March 15, 2019 to Multiple SED Data Requests, Including Portions of Data Request 16 at p. 2. SED initially propounded Data Request 16 February 12, 2018.

⁴⁴³ See Attachment G at p. 2.

1 SED specifically noted that “SoCalGas asserts attorney-client privilege-over
2 communications between SoCalGas and Boots and Coots in entries 3, 5, 7, 9, 12, 13, 14,
3 16, 23, 29, 30, 53 and 54.”⁴⁴⁴

4 As shown by this attorney-client log, several of these communications are between
5 SoCalGas President and CEO, Mr. Bret Lane, and Mr. Clayton, the Boots & Coots team
6 lead, and the same individual SoCalGas did not produce for examination under oath
7 despite SED’s letter and subpoena to do so.⁴⁴⁵

8 On January 3, 2019, SoCalGas supplemented its response to SED Data Request
9 16, stating:

10 As explained in response to Question 1 of SED Data Request
11 34, SoCalGas has agreed to withdraw its claim of privilege
12 and produce certain additional documents that may be
13 responsive to this Request. Without limiting or waiving any
14 other objections asserted, SoCalGas provides the following
15 Supplemental Response to Data Request 16: please see
16 electronic documents with Bates Range
17 AC_CPUC_SED_DR_16_0043471 –
18 AC_CPUC_SED_DR_16_0043550 (continuous) and the
19 following documents (non-continuous).⁴⁴⁶

20 The continuous documents totaled 80 pages.⁴⁴⁷ Making up the non-continuous
21 documents, the response revealed 15 documents that had previously been marked
22 attorney-client privilege-confidential.⁴⁴⁸

⁴⁴⁴ See Attachment G at p. 2, fn. 3.

⁴⁴⁵ See Attachment K-SoCalGas Attorney-client privilege-log in response to SED Data Request 16. For example, see entries 3 and 5.

⁴⁴⁶ See Attachment L-SoCalGas` Supplemental Response Dated March 15, 2019 to Multiple SED Data Requests, Including Portions of Data Request 16 at p. 2. SED initially propounded Data Request 16 February 12, 2018.

⁴⁴⁷ See Attachment G at p. 2.

⁴⁴⁷ Bates number ending in 43550 minus Bates number ending in 43471 equals 80.

⁴⁴⁸ See Attachment L-SoCalGas` Supplemental Response Dated March 15, 2019 to Multiple SED Data Requests, Including Portions of Data Request 16 at p. 2. SED initially propounded Data Request 16 February 12, 2018.

⁴⁴⁸ See Attachment G at p. 3, showing Bates Numbers at top of page.

1 On March 15, 2019, SoCalGas released its claim of privilege on a batch of
2 additional documents, stating:

3 Pursuant to SoCalGas's email communication dated May 11, 2019, SoCalGas has
4 agreed to withdraw its claim of privilege and produce certain additional documents that
5 may be responsive to this Request. Without limiting or waiving any other objections
6 asserted, SoCalGas provides the following Supplemental Response to Data Request
7 16:⁴⁴⁹

8 By SED's count, approximately 18 additional documents were released.⁴⁵⁰

9 Each of the 95 pages that SoCalGas did not release on the grounds of attorney-
10 client or attorney work product privilege is a Section 451 violation because it delayed
11 SED's ability to get this information as part of its pre-formal investigation. These also
12 constitute separate violations of Commission Rule of Practice and Procedure Rule 1.1
13 because SoCalGas represented to SED that these items were protected by attorney-client
14 or attorney work product privilege, when they were not. Each of these violations begin
15 March 5, 2018, the date SoCalGas asserted the privilege to January 3, 2019, the day
16 SoCalGas finally released the documents to SED.

17 The 18 additional communications that SoCalGas did not release until May 11,
18 2019 each constitute their own violation of Section 451 due to the delay they caused to
19 SED's ability to get this information as part of its pre-formal investigation. They also
20 constituted a violation of Rule 1.1 on the grounds that SoCalGas represented to SED that
21 these items were protected by attorney-client or attorney work product privilege, when
22 they were not. Each of these violations begin March 5, 2018, the date SoCalGas asserted
23 the privilege to May 11, 2019, the day SoCalGas finally released the communications to
24 SED.

⁴⁴⁹ See Attachment L-SoCalGas' Supplemental Response Dated March 15, 2019 to Multiple SED Data Requests, Including Portions of Data Request 16, page 3. SED initially propounded Data Request 16 February 12, 2018.

⁴⁵⁰ See Attachment L-SoCalGas' Supplemental Response Dated March 15, 2019 to Multiple SED Data Requests, Including Portions of Data Request 16 at p. 3, showing Bates Number ranges. SED initially propounded Data Request 16 February 12, 2018.

1 **G. Example 4: Blade Asked for Boots and Coots to Appear for Blade to**
2 **Interview Them as Part of Blade’s Root Cause Analysis, But SoCalGas**
3 **Failed to Produce Boots and Coots for This Purpose**

4 On December 19, 2018, Blade requested of SoCalGas that Boots and Coots appear
5 for questions.⁴⁵¹ In response to Blade’s request, SoCalGas asked and re-asked
6 Halliburton to produce Boots & Coots personnel to answer Blade’s questions related to
7 the Root Cause Analysis (RCA) investigation,⁴⁵² reminding Halliburton that Blade’s
8 RCA investigation was independent of SED’s.⁴⁵³

9 However, on January 24, 2019, Boots and Coots’s representative stated in part as
10 follows:

11 As you know, Boots and Coots has been cooperative with the
12 California Public Utilities Commission with respect to the
13 investigation including taking employees to interviews in
14 California at the CPUC to provide testimony in its
15 investigation. Additionally, Boots and Coots has provided a
16 number of documents responded to questions and provided a
17 multitude of information related to its work at Aliso Canyon
18 to California agencies and Southern California Gas.

19 After reviewing the further request for information and
20 interviews from Blade, my client believes that it has provided
21 all of the relevant information related to the Blade inquiry as
22 mentioned above. . .

23 Based on the above, my client is not willing to provide any
24 further information as requested by Blade in its letter.⁴⁵⁴

25 Because SoCalGas failed to contract in its Master Services Agreement with
26 Halliburton and Boots and Coots in a fashion that explicitly required Boots and Coots to
27 address inquiries from Blade in the fashion Blade requested, Boots and Coots did not
28 respond to a direct request from Blade that was within the course of Blade’s duties to

⁴⁵¹ See Attachment M, “Request for Factual Data Verification Discussion December 19th, 2018-Boots and Coots”.

⁴⁵² See Attachment N, “Email thread from SoCalGas outside counsel, James Dragna, to Halliburton’s counsel, Michael Helsley, January 7-8, 2019. See also Attachment Q, “Email Correspondence Between James Dragna (SoCalGas counsel) and Michael Helsley.

⁴⁵³ See Attachment O, “Email thread between SoCalGas outside counsel, James Dragna, Halliburton’s counsels, Timothy Jones and Michael Helsley, January 25, 2019, and February 22, 2019.

⁴⁵⁴ See Attachment P, Letter from Boots and Coots Counsel, Timothy Jones, to SoCalGas Outside Counsel, James Dragna, dated January 24, 2019.

1 perform its Root Cause Analysis. As such, SoCalGas's failure to contract in this fashion
2 violated Section 451. The violation begins on January 24, 2019, the date the Boots &
3 Coots representative refused to produce the Boots & Coots officials, and continues until
4 May 19, 2019, the date of the release of the Blade Report.

5 **H. Example 5: In Response to SED's Question Asking Whether SoCalGas**
6 **Disclosed to Non-SoCalGas Entities Anything that Would Reveal That**
7 **SED Was Conducting EUO's, SoCalGas Revealed that It Had**
8 **Communicated with Counsel representing Pacific Gas and Electric**
9 **Company and Counsel Representing Southern California Edison**
10 **Company**

11 SED asked SoCalGas, "Have any personnel representing or working for Southern
12 California Gas Company disclosed to others who do not work for Southern California
13 Gas Company anything that would reveal that SED is conducting these EUO's?"⁴⁵⁵

14 SoCalGas revealed in response to this data request that, "SoCalGas had
15 conversations with counsel representing the Pacific Gas and Electric Company [PG&E]
16 and counsel representing Southern California Edison Company [Edison] regarding legal
17 principles related to the attendance of counsel at EUOs."⁴⁵⁶

18 In the first SED Examination Under Oath, counsel for SoCalGas clarified, "Just a
19 point for the record based on our off-the record-conversation. First, it's our
20 understanding that the transcript is and shall remain confidential."⁴⁵⁷

21 SoCalGas's discussions about the nature of the presence of counsel at SED's
22 EUO's constitutes a violation of the understanding of SoCalGas counsel to keep the EUO
23 contents confidential, which includes discussing with other utilities whether counsel was
24 present for them. Revealing such information breached SoCalGas's promise to treat the
25 EUO transcripts confidential, and compromised the ability of SED to keep the contents of
26 its safety-related pre-formal investigation confidential, thereby violating Section 451 on
27 two counts; one for each of the two communications with PG&E's and Edison's counsel.
28 In addition, by breaking its promise on the record to keep the contents of SED's EUO

⁴⁵⁵ See Attachment Q, SoCalGas Response to SED Data Request 23, Dated August 14, 2018.

⁴⁵⁶ See Attachment Q at p. 2.

⁴⁵⁷ See Attachment R, Examination Under Oath of Bret Lane at p. 10:27 – 11:3.

1 confidential, SoCalGas violated Commission Rule of Practice and Procedure Rule 1.1.
2 Each violation begins on August 14, 2018, the date that SoCalGas formally disclosed its
3 breach of confidentiality until June 26, 2019, the date SED's pre-formal investigation
4 ended, and the day before the date that the Commission opened the instant proceeding.

5 **I. Example 6: SoCalGas Intentionally Did Not Appear for a Deposition**
6 **Despite of a Commission-Issued Subpoena Requiring It to Do So⁴⁵⁸**

7 SoCalGas intentionally did not appear for a deposition by Safety and Enforcement
8 Division on November 1st, 2019. This is shown by the transcripts of that deposition,⁴⁵⁹
9 and the email correspondence between SoCalGas's and SED's counsel (SoCalGas Intent
10 to Not Appear for Deposition Email).⁴⁶⁰

11 As shown by the "SoCalGas Intent to Not Appear for Deposition Email", SED
12 clarified that:

13 . . . SoCalGas intends to file a motion to quash the subpoena
14 for SoCalGas's person or person(s) most knowledgeable
15 related to the PHC transcripts pages 88-90 and related
16 documents to appear at the Commission headquarters at 505
17 Van Ness Avenue. . . SoCalGas's motion to quash is not
18 sufficient to cancel the deposition. Short of the ALJ granting
19 the motion to quash the subpoena, it is SED's position that
20 SoCalGas is still required to attend the deposition. Failure to
21 do so will constitute another failure on SoCalGas's part to
22 cooperate with the investigation of Safety and Enforcement
23 Division."⁴⁶¹

24 In its response in the SoCalGas Intent to Not Appear for Deposition Email,
25 SoCalGas stated,

⁴⁵⁸ This example occurred during the OII; not the pre-formal investigation. However, SED was unaware that SoCalGas would continue to not cooperate during the OII.

⁴⁵⁹ See Attachment S. Tr. Statement of Non-Appearance, November 1, 2019 at p. 1:5-28.

⁴⁶⁰ See Attachment T. Email correspondence between SED Staff Counsel, Mr. Darryl Gruen, and SoCalGas Senior Counsel, Ms. Avisha Patel, dated October 30 and October 31, 2019.

⁴⁶¹ See Attachment T. SoCalGas Intent to Not Appear for Deposition Email.

1 ██████████ *“SoCalGas has consistently cooperated with SED’s investigation*
2 *and, in fact, that was the purpose of my call yesterday. I left you a*
3 *courtesy voicemail letting you know that were filing our motion*
4 *to quash today so that you could timely cancel the court*
5 *reporter. . .To confirm your understanding: we are filing the*
6 *motion to quash today and we will not be attending the deposition*
7 *tomorrow.”⁴⁶² (Emphasis added).*

8 On October 22, 2019, SED timely served SoCalGas with a subpoena “to have the
9 Person or Persons most knowledgeable at SoCalGas about SoCalGas’ allegations that
10 SED’s “lead investigator” interfered with the RCA into the Aliso Gas leak, appear at the
11 Commission’s offices at 505 Van Ness Avenue, San Francisco at 10:00 a.m. on
12 November 1, 2019.⁴⁶³

13 At SoCalGas’s request, SED met and conferred with SoCalGas once, and in
14 response to SoCalGas’s request to meet again, agreed that SoCalGas could file its motion
15 to quash.⁴⁶⁴

16 By intentionally not appearing at a deposition, SoCalGas impaired SED’s safety-
17 related inquiries in the instant proceeding, thereby violating Section 451. This violation
18 begins November 1, 2019, the date SoCalGas did not show up for the deposition. SED
19 views this violation as not yet having an end date as of the publication of this testimony
20 because SoCalGas has not yet remedied it.

21 **I. SoCalGas Did Not Keep Traceable, Verifiable, Complete or**
22 **Accurate Records That Were Necessary for the Safe Operation and**
23 **Maintenance of Its Wells at Aliso Canyon Natural Gas Storage Facility**
24
25

⁴⁶² See Attachment T. SoCalGas Intent to Not Appear for Deposition Email.

⁴⁶³ See Attachment U-Email from SED Counsel Nicholas Sher to SoCalGas Counsel Sabina Clorfeine providing service of subpoena, and attached subpoena.

⁴⁶⁴ See Attachment V, Email Communication Between SED Counsel Nicholas Sher and SoCalGas Outside Counsel, Pejman Moshfegh, dates October 28, 2019 to October 29, 2019.